



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee	Licensee Representative
MMG Resources Inc.	Theodore Muraro
Licence No. / Expiry	Representative's Title
2BE-IZO1217 (exp. Dec 31 2017)	
Land / Other Authorizations	Land / Other Authorizations
86H/10-1-10   86I/2-1-10	N2012C0005
Date of Inspection	Inspector
12-07-2017	Eva Paul
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Reclamation
	<input checked="" type="checkbox"/> Fuel Storage
	<input type="checkbox"/> Other:

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:	Item No.*	Condition	Observation No.*		
A: SCOPE, DEFINITIONS AND ENFORCEMENT		C	1		
B: GENERAL CONDITIONS		A			
C: CONDITIONS APPLYING TO WATER USE		NA			
D: CONDITIONS APPLYING TO WASTE DISPOSAL		A			
E: CONDITIONS FOR CAMPS, ACCESS INFRASTRUCTURES AND OPERATIONS		A			
F: CONDITIONS APPLYING TO DRILLING OPERATIONS		NA			
G: CONDITIONS APPLYING TO MODIFICATIONS		NA			
H: CONDITIONS APPLYING TO SPILL CONTINGENCY PLANNING		A			
I: CONDITIONS APPLYING TO ABANDONMENT AND RESTORATION OR TEMPORARY CLOSING	I-10	U	2		
J: CONDITIONS APPLYING TO MONITORING		NA			
<i>*The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.</i>					
Samples taken by Inspector:		Location(s):			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input checked="" type="checkbox"/> Action Required (s.3)
<p>An aerial inspection of the above project was conducted on July 12, 2017, followed by an administrative review. This project has been inactive since 2015, using no water and depositing no waste.</p> <p>1. The licence will expire December 31, 2017 but no renewal application is yet seen on file with the Nunavut Water Board. Renewal can take several months. As identified on the licence cover page: “The NWB recommends that an application for the renewal of this Licence be filed at least three months prior to the Licence expiry date.”</p> <p>2. Drill stems are seen within Izok Lake around the island. A plan for removal of these drill stems is required.</p>			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>I-10:The Licensee shall restore all drill holes and disturbed areas to natural conditions immediately upon completion of the drilling. The restoration of drill holes must include the removal of any drill casing materials and if having encountered artesian flow, the capping of holes with a permanent seal.</p>			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
<p>A. The renewal application should be filed as soon as possible, as the process can take several months.</p> <p>B. Please submit to the Inspector a plan (with timelines) for the removal of drill collars/anchors etc. from Izok Lake by March 31, 2018, to be carried out in 2018.</p>			

Licensee or Representative	Inspector's Name
	Eva Paul
Signature	Signature
	Sent electronically
Date	Date
	26-10-2017

CC: Licensing Department, NWB  
Erik Allain, Director of Lands, INAC