

WATER USE INSPECTION REPORT

Date: August 10, 2009	Licensee Rep. (Name/Title): None
Licensee: Aurora Energy / Pacific Ridge	Licence No: 2BE-KAZ0609

WATER SUPPLY

Source(s): Bissett Lake.		Quantity used: -None	
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected			
Intake Facilities: NA	Storage Structure: NA	Treatment Sys: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: Camp is closed at this time. No water consumption on site.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): None

Grey Water: None

Natural Water Body: NA	Continuous Discharge (land or water): NA		
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NA
Periods of Discharge: NA.	Effluent Discharge Rate: NA	

Comments: Camp is closed at this time

Solid Waste: None. Camp is closed. Materials have been consolidated into piles around camp.

Landfill: NA	Burn & Landfill: NA	Other: None
--------------	---------------------	-------------

Comments: Camp is closed at this time.

FUEL STORAGE: 3 Drums containing heating fuel adjacent to three tent frame structures.

Waste Oil Storage: None noted

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: Camp is not in use. Three barrels of fuel noted on site. Three tent frames/ buildings noted on site. Care and maintenance plan is required to maintain and monitor the camp.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator:	
o		INAC: None	
Signs Posted	SNP: None		Warning: NA
Records & Reporting: None			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: A care and maintenance plan is required for the camp. 3 barrels of heating fuel were found on site. Licensee is required to take such actions as are required to prevent the release of hydrocarbons into the environment. A Care and Maintenance plan for the fuel and buildings is required. If camp is not to be reopened the removal of these materials is to be undertaken by the licensee.

A.Keim

Inspector’s Name

Sent by E-mail

Inspector’s Signature