

WATER USE INSPECTION REPORT

Date: July 29th,2008	Licensee Rep. (Name/Title): Mark Warbanski
Licensee: Areva Resources Canada Inc.	Licence No: 2BE-KIG0812

WATER SUPPLY

Source(s): Unnamed Lake	Quantity used: -Records reviewed
-------------------------	----------------------------------

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: A	Storage Structure: A	Treatment Sys: A	Chemical Storage: NA
Flow Meas. Device: A	Conveyance Lines: A	Pumping Stations: NA	Screen : A

Comments: Water for the exploration camp is currently pumped from lake and treated with filters and UV. Records indicate daily checks of system and records of volumes used.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Human waste is burned in Incinerator

Grey Water: Discharged to sump.

Natural Water Body:	Continuous Discharge (land or water): Land		
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA	

Comments: Grease trap and screens are required to remove food particles

Solid Waste:

Landfill: NA	Burn & Landfill: NA	Other: Incinerator & backhaul
--------------	---------------------	-------------------------------

Comments: Records were noted on site and reviewed with licensee.

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality:	Decant Structure:	Erosion: A
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: A
Dams, Dykes: NI	Freeboard: A	Spills:
Construction: NI	O&M Plan:	A&R Plan:
Periods of Discharge: NA.	Effluent Discharge Rate: NA	

Comments: Solid waste is currently being hauled to the mine site for incineration. Some materials are also being hauled to an unlicensed facility in Baker Lake, Nunavut. Waste was piling up in camp, Inspector provided a direction to remove wastes.

FUEL STORAGE:.

Waste Oil Storage: None noted

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: A	

Comments: Secondary Containment noted at Fuel Cache. More may be required in driller’s area in camp. Much positive progress noted since last inspection.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected	Owner /Operator: Areva Resources Canada Inc.

Samples Collected		Owner /Operator: Areva Resources Canada Inc.	
1		INAC: Potable water	
Signs Posted	SNP: None		Warning: U
Records & Reporting: Results of Monitoring to be submitted. Water quality at drill site and release also			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: Areva has a well maintained and clean camp. Two releases of drill cuttings into the environment were noted and sampling is required to ensure no long lasting contamination. Failure on the part of the drilling company to contain cuttings will affect the Licensee. Areva has a daily and weekly monitoring program that should address most issues.

A.Keim

Inspector's Name

Sent by E-mail

Inspector's Signature