



NWB Tools

Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

2BE-KIG1318, N2014C0001 July 23/14 Kiggavik Artesian Flow

1 message

RHINAS Curtis (AREVA) <curtis.rhinas@areva.com>

Wed, Jul 23, 2014 at 4:09 PM

To: "licensing@nunavutwaterboard.org" <licensing@nunavutwaterboard.org>, "andrew.keim@aandc-aadnc.gc.ca" <andrew.keim@aandc-aadnc.gc.ca>, "Rory.Macdonald@aandc-aadnc.gc.ca" <Rory.Macdonald@aandc-aadnc.gc.ca>, "Tracey.McCaie@aandc-aadnc.gc.ca" <Tracey.McCaie@aandc-aadnc.gc.ca>, "Christine.Wilson@aandc-aadnc.gc.ca" <Christine.Wilson@aandc-aadnc.gc.ca>, "sean.joseph@nwb-oen.ca" <sean.joseph@nwb-oen.ca>
Cc: "KINAR Dwayne (AREVA Resources Canada)" <Dwayne.Kinar@areva.ca>, "BLAIN Mario (AREVA Resources Canada)" <Mario.Blain@areva.ca>, "ZUNTI Daniel (AREVA Resources Canada)" <Daniel.Zunti@areva.ca>, "FORSEILLE Stephanie (AREVA Resources Canada)" <Stephanie.Forseille@areva.ca>, "STUMBORG Naomi (AREVA Resources CANADA)" <naomi.stumborg@areva.ca>, "MCCALLUM Barry (AREVA Resources Canada)" <Barry.McCallum@areva.ca>, "ROBBINS John (AREVA Resources Canada)" <John.Robbins@areva.ca>

Good afternoon,

While drilling the non-mineralized hole BONG-066 (UTM 562256E, 7143803N) an artesian flow was encountered at 11:10 AM this morning at a depth of 301m. The initial flow rate was estimated at approximately 4 L/min, but this was very short lived and the rate quickly decreased to 0L/min. Due to the short amount of time that the artesian was present, a water sample was not able to be taken. Drilling is currently continuing at this location and a follow up email will be sent should the artesian return.

Have a nice day

Curtis Rhinas

SHEQ Supervisor, Exploration

AREVA Resources Canada Inc.

Kiggavik Camp: (306) 683-9562

Fax: (306) 343-4632

Curtis.Rhinas@Areva.com