www.inac.gc.ca

www.ainc.gc.ca

Nunavut Regional Office P.O. Box 100 Igaluit, NU, X0A 0H0

Your file - Votre référence NWB2KIR0507 Our file - Notre référence IQA-N 9545-1

May 19, 2006

Phyllis Beaulieu Licensing Administrator Nunavut Water Board P.O. Box 119 Gjoa Haven, NU, X0A 1J0

Re: 2BE-KIR0507 (previously NWB2KIR0507) - Triex Minerals Corporation - Mountain and Dismal Lake Properties - 2005 Annual Report Review

On behalf of the Department of Indian Affairs and Norther Development (DIAND), I have reviewed the 2005 Annual Report, submitted by Triex Minerals Corporation with respect to the Mountain and Dismal Lake Properties.

The 2005 Annual Report mentions centralizing garbage, debris and waste left behind by previous land users. From the information provided it is unclear if clean up work conducted was tailored to preserve local water quality. For instance, waste is commonly stored in a centralized sump or natural depression located no nearer than 30 meters from any water body. Furthermore, the composition and state of garbage, debris and waste are also unknown. Without such knowledge is not possible to determine if the garbage, debris and waste was handled appropriately.

Also, the proponent should updated their Spill Contingency Plan to include Mr. Peter Kusugak, (867) 975-4295 as their INAC contact.

Should you have any questions or comments, please do not hesitate to contact me at (867) 975-4548 or by email at <a href="mailto:BathoryS@ainc-ianc.gc.ca">BathoryS@ainc-ianc.gc.ca</a>.

Sincerely,

Original Signed By

Stephen Bathory Regional Coordinator

cc. P. Kusasugak

