Summary

Coronation Minerals Inc. 347 Bay Street, Suite 301 Toronto, Ont M5H 2R7 Peter Holmes

<u>Diamond Drilling Dismal Lake Area</u> Renewal of Water Licence – NWB2KUG0305

Latitude: N67° 15' to N67° 45' Longitude: W115° 45' to W116° 40'

NTS Map: No.86N

Coronation Minerals Inc. presently holds a water license for a diamond drilling operation in the Dismal Lake area of Nunavut. Logistical and staff availability problems prevented the company from conducting the operation during the summer of 2004.

They are now requesting to an renewal of their existing water license so that they can complete the program in the fall of 2005. All other features of the program will be the same as approved in 2003 by the Nunavut Water Board except the timing.

Nunavut Water Board JUN 2 0 2005 Public Registry

INT	ER	NAL
PC	-	do
MA		
FO	i	THE LANGUAGE SE
LA		OF THE PERSON COMME
88		WTV HURSCON
C.T	m : \$-	C. L. Co. Carrielle
Trail	ĺ	to consideration and the
17-17	- free	Carrier Inc.
1	4.95	7 - Yourseys
()	e in	t comments
CH	*	No. of the State o
BRD	1	Name of the order
EXT.	-	C. Liverbleiter, Na