

**NWB Annual Report**

**Year being reported:** 2006



**License No:** 2BE-MOU0608

**Issued Date:** February 7, 2006

**Expiry Date:** October 31, 2008

**Project Name:** Mouse Lake

**Licensee:** Hornby Bay Exploration Limited

**Mailing Address:**  
Suite 700 - 357 Bay St  
Toronto, Ontario  
M5H 2T7

**Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):**

UNOR Inc - The company's name was officially changed from Hornby Bay Exploration Limited to UNOR Inc on April 26, 2006. Certificate Attached.

**General Background Information on the Project (\*optional):**

The project is focused on exploration for uranium and diamond deposits in the area

**Licence Requirements: the licensee must provide the following information in accordance with**

Part B



**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	Mouse Lake for camp. Drill water intakes attached.	
Water Quantity:	610	Quantity Allowable Domestic (cu.m)
	432	Actual Quantity Used Domestic (cu.m)
	1410	Quantity Allowable Drilling (cu.m)
	1228	Total Quantity Used Drilling (cu.m)

**Waste Management and/or Disposal**

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☒ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

**Additional Details:**

Solid waste incinerated. Ash and non-combustibles disposed in Kugluktuk Waste Management site.  
Sewage - deposited in limed pit toilets.  
Drill waste (cuttings) deposited in sumps in excess of 30 metres from water bodies as per attached table with GPS coordinates.  
Greywater disposed in sump at camp more than 30 metres from Mouse Lake.

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)  
 Date of Spill:   
 Date of Notification to an Inspector:   
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

**Revisions to the Spill Contingency Plan**

SCP submitted and approved - no revision required or proposed



Additional Details:

Addendum to Spill Contingency Plan dated March 1, 2006 submitted as a requirement of Part H, Item 1 of license.

**Revisions to the Abandonment and Restoration Plan**

AR plan submitted and approved - no revision required or proposed



Additional Details:

Addendum to Abandonment and Restoration Plan dated March 1, 2006 submitted as a requirement of Part I, Item 1 of license.

**Progressive Reclamation Work Undertaken**

Additional Details (i.e., work completed and future works proposed)

Drill sites are cleaned up and reclaimed immediately upon completion of drill holes.

**Results of the Monitoring Program including:**

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details attached



Additional Details:

The locations of the 2006 water intake points are depicted on the 1:100,000 scale map titled Coppermine Block, 2006 Drilling and Proposed 2007 Drilling Program that was submitted to the NWB on March 6, 2007

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details attached



Additional Details:

The locations of the 2006 drill holes (sumps) are depicted on the 1:100,000 scale map titled Coppermine Block, 2006 Drilling and Proposed 2007 Drilling Program that was submitted to the NWB on March 6, 2007

**Results of any additional sampling and/or analysis that was requested by an Inspector**

Select



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

Select



Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Select



Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

There were no radioactive intersections in the 2006 drilling that exceeded the minimum uranium content stipulated in Part I, Item 8 of the license.

**Date Submitted:**

March 26, 2007

**Submitted/Prepared by:**

David Bent

**Contact Information:****Tel:** 416 368 0114**Fax:** 416 368 0198**email:** [dbent@unorinc.com](mailto:dbent@unorinc.com)