

NWB Annual Report

Year being reported: 2008



License No: 2BE-MOU0608

Issued Date: February 7, 2006

Expiry Date: October 31, 2008

Project Name: Mouse Lake

Licensee: UNOR Inc.

Mailing Address:
700 - 357 Bay Street
Toronto, ON
M5H 2T7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Original license issued to Hornby Bay Exploration Ltd
Official name change to UNOR Inc registered on April 26, 2006

General Background Information on the Project (*optional):

Uranium exploration on a large block of mineral claims and mining leases located approximately 100 kilometers south of Kugluktuk

Licence Requirements: the licensee must provide the following information in accordance with

Part B



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Mouse Lake & Points Listed in GPS Coordinates Table	
Water Quantity:	525	Quantity Allowable Domestic (cu.m)
	330	Actual Quantity Used Domestic (cu.m)
	1200	Quantity Allowable Drilling (cu.m)
	1150	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☒ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

Solid waste incinerated. Ash and non-combustibles disposed in Kugluktuk Waste Management site.
Sewage - deposited in limed pit toilets.
Hazardous waste including used oil, paint cans, light bulbs, water filter bulb and used batteries was disposed on Oct 3, 2008 under certificate 2485639-5 at Yellowknife Waste Disposal
Drill waste (cuttings) deposited in dumps in excess of 20 metres from water bodies

Drill waste (cuttings) deposited in sumps in excess of 30 metres from water bodies as per attached table with GPS coordinates.
Greywater disposed in sump at camp more than 30 metres from Mouse Lake.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharges occurred
Water meters were installed on the camp and drill intake pumps

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Addendum to Spill Contingency Plan submitted and approved in March 2006

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Addendum to A R plan submitted and approved in March 2006

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

All drill sites are reclaimed as soon as completed
Sites of drill holes HB-07-40 & 41 had additional reclamation work in 2008 and were inspected by INAC on Aug 3/08

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached



Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Inspector requested a temporary closure plan for the season that was submitted on Sept 14/08

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

Report dated Aug 28/08. Included inspection and approval of additonal clean up work requested for drill cuttings from drill holes HB07-40 & 41

Any additional comments or information for the Board to consider

Date Submitted:

Dec-12-2008

Submitted/Prepared by:

David Bent

Contact Information:

Tel: 416-368-0114

Fax: 416-368-0198

email: dbent@unorinc.com