

Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

[Licensing] Re: Mouse Lake camp - heating oil system

1 message

Bogdan Nitescu

 bnitescu@gmail.com>

Mon, Mar 16, 2015 at 3:20 PM

To: Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>

Cc: Baba Pedersen <Baba.Pedersen@aandc-aadnc.gc.ca>, Bogdan Nitescu

Spitescu@hornbybay.com>, Licensing Department Licensing@nwb-oen.ca>, Beverly Brady

Speterly Brady@sympatico.ca>

Hello Eva.

Mr. Jim Brady has been trying to reach you by phone - the Company has identified a contractor and is in the process of trying to make the necessary arrangements for the work. The timing has not been established yet. Once we know the dates when the crew will go there, we will let you know. However, in case you need to discuss further with Jim, please do not hesitate to contact him at 416-423-4850. Thank you,

Decides

Bogdan

On Mon, Mar 16, 2015 at 9:04 AM, Eva Paul < Eva.Paul@aandc-aadnc.gc.ca> wrote:

Thank you Bogdan,

Please let Baba and I know ASAP when the work is scheduled, so we can plan a follow-up inspection after its completion.

Thank you.

Eva

Eva Paul

Water Resources Officer | Agente des ressources en eau Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada Nunavut Regional Office | Bureau régional du Nunavut Building 969, PO Box 2200 | Édifice 969, CP 2200

Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548 Cell | Mobile: 867-222-6490 Fax | Téléc. : 867-979-6445 Eva.Paul@aandc-aadnc.gc.ca

>>> <bnitescu@hornbybay.com> 3/10/2015 7:24:59 PM >>>

TO: Ms. Eva Paul

Water Resources Officer

Aboriginal Affairs and Northern Development Canada

Hello Eva,

The Company management has decided that the heating fuel system at the Mouse Lake camp will no longer be used and will be permanently drained of fuel and dismantled, when work at the camp will be resumed. The fuel that is currently stored in the tanks of the system will be drained into fuel drums and will be handled and dealt with in accordance with the Inspection requirements and all regulations in effect.

The Company will not implement secondary containment to the heating fuel system, since it will be dismantled. As a result, no addenda addressing spill preventative measures through secondary containment and temporary shut-down measures in the case of this system will be added to the Company's Spill Contingency Plan and the Abandonment and Restoration Plan.

For further information on the the aspects addressed in this message, please contact Mr. James Brady, President and CEO of Hornby Bay Mineral Exploration Ltd., at 416-423-4850.

Best regards, Bogdan

Bogdan Nitescu, PhD, PGeo Hornby Bay Mineral Exploration Ltd. 416-574-3553