

WATER USE INSPECTION FORM

\leq	Original	
	Follow-Up	Report

Licensee Licensee Representative												
Commander Resources Ltd Robert Cameron/Tara Gunson												
Licence No. / Expiry Representative's Title												
2BE-NAD1722												
Land / Other Authorizations Land / Other Authorizations												
Date of Inspection Inspector												
August 14, 2	2017			Justin	HACK							
Activities Inspected Camp	☐ Drillin	σ	Mining	☐ Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage								
Roads/Hauling	Other	Other:			Neciamat] heciamation						
Conditions: A - Acceptable (C - Concern U - Unacceptable			NA – Not Applicable NI – Not Inspected						
Water Use	-			- опассер				•				
	Conditi	on Comment	Site Conditions	Ctructuros	Condition		Management	Condition	Comment			
Intake/Screen	A		Water Management	Structures	NA	Storage		A				
Flow Measure. Do			Culverts / Bridges		NA	Spills		A				
Source:	A		Drainage		Α	Spill Plan		Α				
Water Use:	Α		Erosion / Sediment		Α							
Recirculation (y /	/n) NA		Mitigation Measur		NA	Administ	trative					
			Reclamation Activi	ties	NA	Records		Α				
			Materials Storage		Α	Reports		Α				
Waste Disposal			Signage		NA	Plans		NI				
Waste Water	А					Notificat	ions	NI				
Solid Waste	A		Monitoring			Other						
Hazardous Waste	e NA		Sample Collection	/ Analysis	NA							
	*The num	ber in the co	omments field will co	orrespond v	vith speci	ific comments prov	ided below.					
Samples taken by	/ Inspector:		Location(s):									
☐ Yes ☐ No												
SECTION 1	⊠ Comr	nents (s.1)	Non-Con	npliance w	th Act or	r Licence (s)	Action Re	equired (s)			
Background												
Commander Resource Ltd has been issued a Type B Water Licence (2BE-NAD1722) for the use of 2m ³ per day of water and the												
			nd related activities									
Photo 1). This lice	ence is valid u	ntil July 17, 2	2022.									
Inspection Repor	rt											
	-											
Water Use												
		_	ter from the stream			•	В.					
•	•	•	inment and water q		_		_					
			tion was occurring a e pump hose (see P		related	to this use of water	r.					
	as a screen at	tached to th	e pump nose (see r	11010 2 j.								
Waste Disposal												
5. Greywat	ter was being	directed to a	a sump located grea	ter than 31	m from t	he stream (see <i>Pho</i>	oto 3).					
		_	in a way in which it		effect ir	nland waters.						
7. Sewage	wastes were	being contai	ned within Pacto toi	ilets.								
Other notes:												
8. All fuel c	on site was co	ntained with	nin secondary contai	inment or s	reater th	an 31m from the n	earby river.					
			ime of the inspection	_			-					
	were noted.		·		_							
Click here to e	enter text											
SECTION 2		ments (s 2	Non-Con	nnliance wi	th Act or	rlicence (s)	Action Re	auired (s	12)			
SECTION 2 Comments (s2_) Non-Compliance with Act or Licence, (s) Action Required (s.12) There were no concerns noted related to this Licensee's use of water or deposit of waste												
There were no concerns noted related to this dicensee's use of water of deposit of waste												
Inspector's Name												
Justin Hack												
Signature												
, ~	\											



Date

September 26, 2017



Photo 1: Overview of camp.



Photo 2: Water pump with intake screen in blue.





Photo 3: Sump where greywater is discharged.

