



☒ Original  
☐ Follow-Up Report

LAND USE PERMIT INSPECTION FORM

Permittee	Representative
Northquest Ltd.	Dwayne Carr
Permit No. / Exploration / Expiry	Representative's Title
N2011C0014/ June 14 <sup>th</sup> , 2016	P. Geo
Other Authorizations	Land / Other Authorizations
2BE-PBP1115	IOL Authorization/ Municipal Lands
Date of Inspection	Inspector
07/06/2015	WRO Wilson
Activities Inspected	
<input type="checkbox"/> Camp	<input checked="" type="checkbox"/> Drilling
<input type="checkbox"/> Roads/hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input type="checkbox"/> Other:
	<input checked="" type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
Section:	Term No.	Condition	Observation No.		
31 (1)(a) Location and Area	4	A	-----		
31 (1)(b) Time	7	A	----		
31 (1)(c) Equipment	--	--	-----		
31 (1)(d) Methods and Techniques	--	--	-----		
31 (1)(e) Type location, capacity and operation of facility	19	U	1 (a), 2(a)&(b)		
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land	30, 31	A	1(d), 2(d)		
31 (1)(g) Use, storage, handling and disposal of chemical or toxic materials	39	--	**		
31 (1)(h) Wildlife and fisheries habitat	--	--	-----		
31 (1)(i) Objects and places of recreation, scenic and ecological value	--	--	-----		
31 (1)(k) Petroleum fuel storage	--	--	-----		
31 (1)(m) Matters not inconsistent with the regulations	--	--	-----		

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Land Use Permit No. N2011C0014 was issued to Northquest Ltd. for exploration work at Pistol Bay Project. This permit is for use of land related to drilling and does not include the camp or fuel storage area.			
On July 6 <sup>th</sup> , 2015 two drill sites authorized under N2011C0014 were inspected by WRO Wilson.			
Pre inspection meeting notes			
<ul style="list-style-type: none"><li>- Majority of the drill hole depths are less than 100 m which subsequently reduces the overall drill waste.</li><li>- The cuttings are left in low lying areas proximal to the hole. Northquest suggests this practice aids natural vegetation to regenerate faster.</li><li>- Drill water is metered at the pump and recorded. Water use includes recirculation totals.</li><li>- Two drills operating this year, with the program starting once the water licence renewal has been issued.</li><li>- The majority of Northquest's, Pistol Bay project area is within municipal boundaries with only two drill sites in 2014 located on crown land.</li></ul>			
Observations			
<ol style="list-style-type: none"><li>Drill hole no. BH14-05, (N62° 21' 33.2" W93° 04' 09.9" approximate area)<ol style="list-style-type: none"><li>drill rod left in place, about 1 ft remains above ground</li><li>cutting around hole</li><li>clean site, no garbage.</li><li>no rutting around drill site</li></ol></li><li>Drill hole no. BH14-04, (N62° 21' 34.2" W 93° 04" 30.6" approximate area)<ol style="list-style-type: none"><li>some garbage around hole</li><li>drill rod left in place, sticking out of the ground</li><li>cutting around hole</li><li>no rutting around drill site</li></ol></li></ol>			
NOTE: 31(1) (g) item 39 regarding burial of garbage longer forms part of this permit.			
31 (1) (e) item 16 regarding drill sump freeboard no longer forms part of this permit.			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
31(1)(e) item 19 –Failure to reclaim drill holes			
“The Permittee shall ensure all drill holes are backfilled or capped prior to the end of each field season.”			

SECTION 3		<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input checked="" type="checkbox"/> Action Required
<p>The Inspector was pleased with the overall condition of the drill sites, the proponent will complete final inspection of all drill sites on crown land to ensure drill rods/anchors are reclaimed and any garbage and debris removed. Final reclamation activities will be completed during the 2016 field season with the information provided to the Engineer of Lands, Aboriginal Affairs and Northern Development Canada in the 2016 annual report.</p> <p>It is the responsibility of Northquest to contact the inspector if there is an issue with fulfilling the required actions found in this report.</p>				
Licensee or Representative		Inspector's Name		
		WRO Wilson		
Signature		Signature		
		Original signed on file		
Date		Date		
		July 7 <sup>th</sup> , 2015		

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
------------------	--	------------------------------	--

Cc’ Erik Allain, Manager, Field Operations, AANDC  
Manager Land Administration, AANDC  
Dwayne Car, Northquest  
Jon North, Northquest

Attch: Photo Log





Date	Camera	Inspector	Authorization
July 6 <sup>th</sup> , 2015	Sony Cyber Shot DSC-HX50V	WRO Wilson	N2011C0014
Photo Log #	Location (NAD 83 DD MM SS.SS)		
Photo 1	N 62° 21' 32.54" W93° 4' 30.68"		
			
Description:			
Drilling materials left protruding from ground			

Photo Log #	Location (NAD 83 DD MM SS.SS)
Photo 2	N 62° 21' 32.652`` W 93° 4' 30.689``
	
Description:	
Small amount of debris at drill site	