

\boxtimes	Original
	Follow-Up Report

LAND USE PERMIT INSPECTION FORM

Permittee Representative				
Northquest Ltd. (Nord Gold SE) David Smith				
Permit No. / Expiry Representative's Title				
N2016C0007 / 07-20-2021 Exploration Manager, Nord Gold SE				
Other Authorizations Land / Other Authorizations				
2BE-PBP1520 Date of Inspection Inspector				
August 1 st , 2019 WRO C. Wilson				
Activities Inspected				
☐ Campsite ☐ Drilling ☐ Mining ☐ Construction ☐ Roads/hauling ☐ :Other:	Reclama	ation	Fuel Storage	
Conditions: A- Acceptable U-Unacceptable C-Concern	NI-Not Inspe		Not applicable	
Section:	Term No.	Condition	Observation No.	
31 (1)(a) Location and Area		A		
31 (1)(b) Time	7,10	A,A	1,2	
31 (1)(c) Equipment				
31 (1)(d) Methods and techniques 31 (1)(e) Type location, capacity and operation of facility	17 18,19, 21	<u>А</u> А	3	
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land	10,19,21			
31 (1)(g) Use, storage, handling and disposal of chemical or toxic materials				
31 (1)(h) Wildlife and fisheries habitat				
31 (1)(i) Objects and places of recreational, scenic and ecological value				
31 (1)(k) Petroleum fuel storage				
31 (1)(m) Matters not inconsistent with the regulations				
SECTION 1 Comments Non-Compliance with Ac	t or Licence	Action	Required	
Land use permit no. N2016C0007 is issued to Northquest Ltd. for the use of lar			•	
permittee') name. The Pistol Bay project extends over three different land jurisdictions- the Crown, the Kivalliq Inuit Association and the Hamlet of Whale Cove. On August 6th, 2019 a compliance inspection was conducted of three drill sites, located on the Crown land portion of the project. This report was produced with the information provided by the permittee in the 2018 annual report and the findings of the inspection.				
Observations				
1. The permittee provided notice to the inspector prior to the commencement of the land use operation in accordance with section 31(1)(b) item 7 and 9.				
2. The 2018 annual report was submitted in accordance with 31(1)(b) item 10.				
3. Drill holes PB-16-17, PB-16-31 were inspected. All three sites were clean and reclaimed and in accordance with 31(1)(b) item 17.				
SECTION 2 Comments Non-Compliance with Ac	ct or Regulations	Action	Required	
Non-compliance or failures to comply related to the conditions of Land Use Permit no. N2016C0007; — None				
SECTION 3 Comments Non-Compliance with Ac	t or Regulations		Required	
The permittee has met all requirements of the permit at the time of this inspection.				
Licensee or Representative Inspector's N	lame			
RMO W	'ilson			
Signature Signature				
•	l signed on fil	е		
Date Date	24th 2010			
	26 th , 2019			
Office Use Only: Follow-up report to be issued by Inspector	☐ Yes 🖂	INO		

