Affaires indiennes et du Nord Canada

www.inac.gc.ca www.ainc.gc.ca

Nunavut Regional Office P.O. Box 100 Igaluit, NU, X0A 0H0

Your file - Votre référence NWB2REG0406 Our file - Notre référence IQA-N 9545-1

May 23rd, 2006

Phyllis Beaulieu Licensing Administrator Nunavut Water Board P.O. Box 119 Gjoa Haven, NU, X0A 1J0

Re: 2BE-REG0406 (previously NWB2REG0406) -Strongbow Exploration Inc.-Regan Lake Project - 2005 Annual Report Review

On behalf of the Department of Indian Affairs and Norther Development (DIAND), I have reviewed the 2005 Annual Report, submitted by Strongbow Exploration Inc. for the Regan Lake Project with respect to License NWB2REG0406 (License).

Part D, Item 5 of License states that the proponent shall contain all sewage in latrine pits located at least 30 meters above the ordinary high water mark of any water body. The item goes on to state; these latrine pits shall be treated with lime and covered with native material. It is unclear from the 2005 Annual Report if these actions were taken.

Also, the proponent should updated their Spill Contingency Plan to included Mr. Peter Kusugak, (867) 975-4295 as the INAC contact.

Should you have any questions or comments, please do not hesitate to contact me at (867) 975-4548 or by email at <a href="mailto:BathoryS@ainc-ianc.gc.ca">BathoryS@ainc-ianc.gc.ca</a>.

Sincerely,

Original Signed By

Stephen Bathory Regional Coordinator

cc- P. Kusugak

