



WATER USE INSPECTION REPORT

(continued)

Date: 1 Aug 2008

Rockgate

Licence #: 2BE-ROK

General Comments: (Continued)

Company Rep: Mike Roberts Manager P. Geo (ON)

At Bathurst Inlet → fuel drums should be in ^{appropriate} secondary containment and drums are being reused onsite by community members (at Lodge) with Rockgate label on drum.

- Containers left in community must be labelled appropriately and secured (white containers located - possibly from drillers?) → placed in secondary containment where appropriate - this includes waste containers

- Fuel drums or wastes not to be stored within 30m of water or high water mark

- All ~~haz~~ wastes must be removed to an approved landfill site → cannot be left in Bathurst Inlet

- Silt fencing to be used where appropriate at drill site

- Pumps and jerry cans to be placed in secondary/drip containment; spill kits to be located ^{mg} in easily accessible locations.

- Sewage to either be placed in appropriate containment (lined region) or ^{mg} approved from NWB for must be disposed of off site appropriately

- Volume of water used - flow meter installed and volume recorded at designated intervals (daily, weekly, etc)

- Unable to locate drill site with coordinates provided → Turner Lake

↳ will try another pass on way back to Yellowknife ^{mg}

[Signature]

[Signature] (MELISSA JOY)
Water Inspector