

WATER USE INSPECTION REPORT

Date: July 30th,2008	Licensee Rep. (Name/Title): Doug McLeod (Matrix)		
Licensee: Western Uranium Corp.		Licence No: 2BE-SAN0709	

WATER SUPPLY

Source(s): Sand Lake	Quantity used: 2450 Gal – Records noted
Owner:/Operator: Matrix Logistics for W.U.C.	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NI	Storage Structure: A	Treatment Sys: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: Water for the exploration camp is -treated with UV and Filtration at the Exploration Camp. The Water intake pump is not metered and this must be addressed by the next Inspection.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec./Ter.): Incineration

Natural Water Body: NA	Continuous Discharge (land or water):NA	
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA

Comments: Incinerator noted on site.

Solid Waste:

Landfill: NA	Burn & Landfill: NA	Other: Incinerator & backhaul
---------------------	--------------------------------	--------------------------------------

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: A
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: A
Dams, Dykes: NI	Freeboard: A	Spills: NA
Construction: NI	O&M Plan: NI	A&R Plan: NI
Periods of Discharge: NA.	Effluent Discharge Rate: NA	

Comments: An Incinerator is on site. Hazardous wastes are back hauled to Baker Lake.

FUEL STORAGE:.

Waste Oil Storage: None noted

Owner/Operator: Western Uranium Corp.

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: NA	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: Secondary Containment was noted at the camp. 200 Plus barrels of assort fuels in Secondary Containment.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected : 0		Owner /Operator: Uranium North resources Ltd.	
Samples Collected : 0		INAC:	
Signs Posted	SNP: None	Warning: U	
Records & Reporting: Annual reporting is required			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: The Camp is well laid out and clean. The sumps were covered and there were no signs of overland flow. Bear fence encircles camp. Fuel is stored properly. Overall an excellent and well maintained camp.

A.Keim

Inspector's Name

Sent by E-mail

Inspector's Signature