

**WATER LICENCE INSPECTION FORM**☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Forum Uranium Corp.	Ken Wheatley
Licence No. / Expiry	Representative's Title
2BE-SCH0712/ September 27 th , 2012	Exploration
Land Authorization No. / Expiry	Land Authorization Expiry
N2014C0010/ February 22 nd , 2017	KVL307C01 (expired)
Date of Inspection	Inspector
August 2nd, 2019	RMO C. Wilson
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Airstrip
<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Other:	

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
On August 1 st an inspection was conducted of water licence no. 2BE-SCH0712 by Crown-Indigenous Relations and Northern Affairs Canada. Photos of this inspection were lost due to a technical issue.			
The following report was produced with information from the inspector's notes and post inspection discussions with the licensee.			
PRELIMINARY NOTES			
— The water license expired in 2012.			
— This water license was issued for exploration purposes only; no camp was authorized under this licence.			
— The Licensee purchased a camp and had it moved to its current location at Judge Sissons Lake at N64° 16' 29", W94° 32' 14". The camp though associated with this project is not authorized under this water licence and was never utilized by the Licensee.			
OBSERVATIONS			
1. The 2007-2012 annual reports are available for review on the Nunavut Water Board's FTP website, in accordance with PART B item 2.			
2. The camp located at Judge Sissons Lake, N64° 16' 29", W94° 32' 14" had been removed.			
SECTION 2	<input type="checkbox"/> Comments (s. __)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
No compliance issues noted at the time of inspection.			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s.3)
ACTIONS REQUIRED			
Based on the findings of this inspection and the information provided by the licensee, Crown-Indigenous Relations and Northern Affairs Canada has determined that this will be a final inspection.			

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
	Sent by e-mail
Date	Date
	August 29 th , 2019

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---