

NWB Annual Report

Year being reported: 2009 ▼

License No: 2BE-SCH0712 **Issued Date:** September 27, 2007
Expiry Date: September 30, 2012

Project Name: North Thelon Joint Venture (Schultz Lake Project)

Licensee: Forum Uranium Corporation

Mailing Address: #910 - 475 Howe Street, Vancouver, BC V6C 2B3

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Forum Uranium Corporation

General Background Information on the Project (optional):

Please refer to Forum Uranium's file on the NIRB ftp site for details.
 LINK:
http://ftp.nunavut.ca/nirb/NIRB_SCREENINGS/COMPLETED_SCREENINGS/ARCHIVE/2007_SCREENINGS/07EN046-Forum_Uranium_Corporation/1-SCREENING/

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	NONE	
Water Quantity:	5	Quantity Allowable Domestic (cu.m)
	0	Actual Quantity Used Domestic (cu.m)
	40	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

All 2009 operations were based out of Baker Lake Lodge in Baker Lake, NU. As such no water was drawn from any waterbodies on the North Thelon Project. No drilling was conducted and no field camp was utilized. No wastes were disposed of outside of the normal operation of the Baker Lake Lodge.

A list of unauthorized discharges and a summary of follow-up actions taken.Spill No.: (as reported to the Spill Hot-line)Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills occurred during Forum Uranium Corp's operations in 2009.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

No revisions required or proposed.

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

No revisions required or proposed

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

1. Forum addressed issues found during KIA's 2008 inspection of Tanqueray Resources' Thom Lake camp (then occupied by Tanqueray) as Forum is associated with the site:

- improperly stored fuel drums were moved to the containment berm
- fuel-contaminated soil that seeped from a leaky drum was excavated and also stored in the berm.

2. Junk and debris surrounding an old exploration camp at 64° 25' 32"N / 97° 2' 26" W was collected and stored inside a derelict building there

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

No water was drawn from any waterbodies on the North Thelon Project in 2009.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Not Applicable (N/A) ▼

Additional Details:

No wastes were disposed of outside of the normal operation of the Baker Lake Lodge in 2009.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Though Forum Uranium took it upon themselves to deal with some of the issues four at Thom Lake camp during KIA's 2008 inspection, Forum was not operating the camp at the time or since and the issues were not a result of actions taken by Forum personnel. However, as Forum has rented this camp in the past and now has their name associated with it, it was seen to be in Forum's best interest to act on this.

Date Submitted:

March 31, 2010

Submitted/Prepared by:

Anthony Williamson, Forum Uranium Corp.

Contact Information:

Tel: 250-897-8000

Fax: 604-689-3609

email: a.williamson@forumuranium.com