

P.O. Box 119 GJOA HAVEN, NU X0B 1J0 TEL: (867) 360-6338 FAX: (867) 360-6369 בּבְּי בּרְבְיְי לּהְרִי לּהְרִי לּהְרִי לּהְרִי לּהְרִי לְּתְרִי לְּתְרִי לְּתְרִי לְּתְרִי לְּתְרִי לְּתְרִי לְּתְרִי לְּתְרִי לְתְרִי לְתְרְים לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרְים לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרִי לְתְרְים לְתְּרְים לְתְּרְים לְתְּרְים לְתְּרְים לְתְּרְים לְתְּים לְתְּרְים לְתְּים לְתְּרְים לְתְּים לְתְּרְים לְתְּים לְתְּרְים לְתְּרְים לְתְּים לְתְּים לְתְּרְים לְתְּים בּתְּים לְתְּים לְתְּים לְתְּים לְתְּים לְּתְּים לְתְּים לְתְּים בּיוּים לְּתְים בּיוּים בּיוּים בּיוּים בּיוּים בּיוּים בְּיבְים בְּיבְים בְּיבְים בְּיבְּים בְּיבְים בְּיבְים בְּיבְים בְּיבְי

File: 2BE-SCH0712/TR/B2, H2, I2

November 01, 2010

Anthony Williamson Project Manager - Nunavut Forum Uranium Corp. 910-475 Howe Street Vancouver BC V6C 2B3

E-mail: a.williamson@forumuranium.com

Subject: Licence No. 2BE-SCH0712 "Schultz Lake Project" - Forum Uranium

Corporation; Submission of the 2008 Annual Report with the Addendums to

the Spill Contingency and Abandonment and Restoration Plans

Dear Mr. Williamson:

The Nunavut Water Board ("NWB") has completed a technical review of the 2008 Annual Report for the above-mentioned project, which was received on September 23, 2010 with the Addendums to the Spill Contingency (Appendix 12), and Abandonment and Restoration (Appendix 11) Plans. Also included with the report are:

- Appendix 1 RESOLVETM Survey Method;
- Appendix 2 Ground Gravity Survey Method;
- Appendix 3 Drill Hole Summary;
- Appendix 4 Camp and Fuel Cache Locations;
- Appendix 5 Wildlife & Archaeological Sightings;
- Appendix 6 Camp Photos;
- Appendix 7 List of Field & Office Personnel;
- Appendix 8 List of Service Companies;
- Appendix 9 Community Consultations and Information Sessions;
- Appendix 10 Field Inspections.

The submission was distributed for information. No comments were received regarding the submission.

NWB conducted technical reviews on the Annual Report, Revised Spill Contingency and Abandonment and Restoration Plans determined that all three documents are acceptable and consistent with the terms and conditions in Licence 2BE-SCH0712.

However, the Section **5.3 Basic Steps** – **Chain of Command** of Spill Contingency Plan indicates that the contact information (867) 975-4298 for DIAND Water Resources Inspector in Nunavut. The correct contact information should be stated as follows: **(867) 975-4295**.

Should you have any questions, please feel free to contact the undersigned at (867) 360-6338 Ext. 30, at your earliest convenience.

Yours truly,

Original Signed By:

Karén Kharatyan Technical Advisor

cc: Distribution List – Kivalliq