



NWB Tools

Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

2BE-SIL0709 Inspection Report - Strongbow Exploration, Silvertip Property

1 message

Mike MacMorran <mikemacmorran@gmail.com>

Wed, Dec 18, 2013 at 4:12 PM

To: Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>

Cc: Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

Hi Eva,

My name is Mike MacMorran and I am writing in regards to Strongbow Exploration's water license (2BE-SIL0709) for the Silvertip property in Nunavut. I'm a relatively new employee to the company and have been tasked with addressing any outstanding water board compliance issues - we've had some correspondence regarding other licenses held by both Strongbow and North Arrow Minerals already.

In your inspection report for license 2BE-SIL0709 under the section Action Required you wrote "If you would like copies of Ms. Joy's 2009 photos." - I'm assuming that there are more photos from the 2009 site inspection. If there are in fact more photos, can you please forward them onto me along with any comments Ms. Joy may have included (i.e. Thlewycho Lake looking east; remnant of old Mouse Lake camp; etc.).

Much appreciated!

Mike