



## WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

<b>Licensee</b>	<b>Licensee Representative</b>
Golden Bull Resources Corp.	-
<b>Licence No. / Expiry</b>	<b>Representative's Title</b>
2BE-SLA0814	-
<b>Land / Other Authorizations</b>	<b>Land / Other Authorizations</b>
<b>Date of Inspection</b>	<b>Inspector</b>
15/07/2014	Eva Paul
<b>Activities Inspected</b>	
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: <input type="checkbox"/> Other:	

**Conditions:**      **A - Acceptable**      **C - Concern**      **U - Unacceptable**      **NA – Not Applicable**      **NI – Not Inspected**

Water Use			Site Conditions			Haz/Mat Management		
Condition	Comment		Condition	Comment		Condition	Comment	
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NA	
Water Use:	NA		Erosion / Sediment	NA				
Recirculation ( y /n)	NA		Mitigation Measures	NA		<b>Administrative</b>		
			Reclamation Activities	NA		Records	A	
			Materials Storage	NA		Reports	U	
<b>Waste Disposal</b>			Signage	NA		Plans	A	
Waste Water	NA					Notifications	A	
Solid Waste	NA		<b>Monitoring</b>			<b>Other</b>		
Hazardous Waste	NA		Sample Collection / Analysis	NA				

*\*The number in the comments field will correspond with specific comments provided below.*

<b>Samples taken by Inspector:</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>Location(s):</b> <div style="height: 20px;"></div>
---	--

<b>SECTION 1</b>	<input checked="" type="checkbox"/> <b>Comments (s.1)</b>	<input checked="" type="checkbox"/> <b>Non-Compliance with Act or Licence (s.2)</b>	<input checked="" type="checkbox"/> <b>Action Required (s.3)</b>
<p>On July 15 2014 an inspection was conducted on sites related to 2BE-SLA0814. Four camps are authorized under this licence. A preliminary inspection for cancellation of this licence occurred in 2012; however, verification of the coordinates was needed and the inspection was completed in 2014. The following sites were inspected:</p> <p>a) Penthouse Camp* - N66°53'46.0" W110°54'47.0"</p> <p>b) Esker Lake Camp - N66°50'48.0" W110°56'46.0"</p> <p>c) East Arm Contwoyto - Lake N65°47'24.0" W110°43'33.0"</p> <p>d) Hecla Camp* - N65°48'42.0" W110°39'23.0"</p> <p>Legacy materials were found at site a) consisting of old core racks and cement pilings. Site d), the historic Hecla camp, was found to contain old core racks and fuel barrels (2 full and several empties), however the era of the camp clearly pre-dates this licence and the camp's existence was identified in the application. I do not believe that these materials are associated with this licence.</p> <p>Sites b) and c) showed no signs of use.</p>			

**SECTION 2**☐**Comments**☒**Non-Compliance with Act or Licence**☐**Action Required**

Part B Item 2. Failure to file Annual Reports.

**SECTION 3**☐**Comments**☐**Non-Compliance with Act or Licence**☐**Action Required**

Cancellation procedures were not completed after Mr. Goad left the project, and no annual reports have been filed since 2011.

No further inspection of this licence is required. When the NWB is satisfied that administrative requirements have been met, this licence can be cancelled.

<b>Licensee or Representative</b>	<b>Inspector's Name</b>
	Eva Paul
<b>Signature</b>	<b>Signature</b>
	<i>Sent electronically</i>
<b>Date</b>	<b>Date</b>
	5/12/2014

**APPENDICES:**☐**Inspection Photos**☐**Sample Results**☐**Other:**☐

Office Use Only:

Follow-up report to be issued by Inspector

☐

Yes

☒

No

CC:

Phyllis Beaulieu, Manager of Licensing, NWB

Erik Allain, Manager of Field Operations, AANDC