

## WATER LICENCE INSPECTION FORM

Original
Follow-Up Report

Licensee Representative								
Mega Uranium Limited None								
Licence No. / Expiry Representative's Title								
2BE-THE0813		•						
Land / Other Authorizations								
N2013U0006								
Date of Inspection Inspector								
18/07/2014		Justin	HACK					
Activities Inspected								
☐ Camp ☐ Drilling			nstruction	☐ Reclamation	☐ Fuel Storage			
Roads/Hauling Conditions: A - Ac	Other: cceptable	C - Concern U - Unaccep	ner: table	NA – Not Applicable	NI – Not Inspe	cted		
Water Use	Condition Comr		Condition	Comment Haz/Mat Manage	•	Comment		
Intake/Screen	NA	Water Management Structures	NA	Storage	NA			
Flow Measure. Device	NA NA	Culverts / Bridges	NA	Spills	NA			
Source:	NA	Drainage	NA	Spill Plan	NA NA			
Water Use:	NA NA	Erosion / Sediment	NA	opin riuri	1471			
Recirculation ( y /n)	NA	Mitigation Measures	NA	Administrative				
Recirculation ( y / ii)	INA	Reclamation Activities	A	Records	А			
		Materials Storage	NA NA		A			
Wests Disposal		•		Reports Plans				
Waste Disposal	NIA	Signage	NA		NA			
Waste Water	NA			Notifications	NA			
Solid Waste	NA	Monitoring	210	Other				
Hazardous Waste	NA	Sample Collection / Analysis	NA					
4.7			<u> </u>					
*11	he number in t	the comments field will correspond	with speci	fic comments provided below	N.			
SECTION 1								
	Comments	Non-compliance w	itti Act oi	Licerice Act	ion Required			
<u>Background</u>								
		to cancel their Water Licence 2BE-						
provides a summary of the remediation activities associated with the closure of their Itza Lake camp at GPS coordinates: 65°02′25″N								
and 98°22′26″W. On July 18, 2014 an inspection of their campsite was conducted to confirm that remediation was conducted								
according to their Abandonment and Restoration Plan and that no major obligations under their water licence remain.								
Observations on Site								
1. No infrastructure remained on site, except for four core boxes now the property of NexGen Energy.								
<ol><li>Wooden infras</li></ol>	tructure appea	ars to have been burned and there	are small i	traces of ash on the ground.				
		ng the inspection.						
4. It appears that	the ground ha	as been contoured to a more natura	ıl state.					
Inspector's Stateme	ent							
		to AANDC through correspondence	es record	ls and site inspections no c	oncerns were not	ed		
Based on the evidence made available to AANDC through correspondences, records, and site inspections, no concerns were noted with the site, and the project is recommended to proceed with cancellation.								
, p 3,								
Inspector's Name								
Justin Hack								
Signature								
Justin La.								
Data								



July 18, 2014