



Field Operations  
Nunavut Regional Office  
PO Box 100  
Iqaluit, NU X0A 0H0

September 26, 2012

Karl Kottmeier, President  
Bama Gold Corp. (was Rockgate Capital Corp.)  
1450-701 West Georgia Street  
Vancouver, BC  
V7Y 1G5

RE: NWB Licence No. 2BE-TRN0813

Dear Mr. Kottmeier,

I was present at your site on July 13, 2012. Please find attached the report of my inspection. I contacted Mr. Boyd Warner at your recommendation and he was not able to produce any of the information I requested regarding your programs. I will require that you follow up with the appropriate person to find the information required for this file, as outlined below.

I require that you submit documentation of the name change from Rockgate Capital Corp. to Bama Gold Corp. by October 31. This is to be submitted to myself and the Nunavut Water Board.

Please feel free to contact me to discuss the timelines outlined in this report.

Thank you,

Eva Paul  
Water Resources Officer

Phone: 867-975-4548  
Fax: 867-979-6445  
Mobile: 867-222-6490  
E-mail: [Eva.Paul@aadnc-aadnc.gc.ca](mailto:Eva.Paul@aadnc-aadnc.gc.ca)

Cc: Andrew Keim, A/Manager, Field Operations, Nunavut Regional Office  
Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board



## WATER LICENCE INSPECTION REPORT

Date: July 13 2012	Licensee Rep. (Name/Title): N/A
Licensee: Bama Gold Corp.	Licence No.: 2BE-TRN0813

### WATER SUPPLY

Source(s): NA	Quantity used: n/a
Owner:/Operator: Karl Kottmeier	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

**Comments:** No evidence of a camp at this site. A few core boxes are all that are present.

### WASTE DISPOSAL

**Sewage:** Sewage Treatment System (Prim./Sec/Ter.): N/A

Natural Water Body: -	Continuous Discharge (land or water): -	
Seasonal Discharge: -	Wetlands Treatment: -	Trench: -

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NA
Discharge: NA	Effluent Discharge Rate: NA	

**Comments:** N/A

### Solid Waste:

**Owner/Operator:**

Landfill: NA	Burn & Landfill: NA	Other: Backhaul
--------------	---------------------	-----------------

**Comments:** A few pieces of plywood mark what may have been this site; core boxes remain nearby. Significant legacy fuel and garbage is evident nearby (Chevron) which has been documented by AANDC Contaminated Sites.

### FUEL STORAGE:

**Waste Oil Storage:**

**None**

**Owner/Operator:** Licensee

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: U	Water within Berms: NA	Evidence of Leaks: NA
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

**Comments:** Fuel at Chevron site is assumed to be unrelated to this licence.

### Non-Compliance of Act or Licence:

No annual reports are on file with the NWB for this licence. Annual reports must be filed for every year, whether or not activity occurred. GPS coordinates for drilling locations are to be submitted with the appropriate report, as well as the accurate historic camp location. All missing annual reports are to be completed and submitted by March 31 2013.

Documentation of the name change from Rockgate Capital Corp. to Bama Gold Corp. is to be submitted to the Inspector and to the Nunavut Water Board by October 31, 2012.

Failure to comply with this report may result in enforcement action being taken.

Eva Paul  
Inspector's Name

  
Inspector's Signature