

NWB Annual Report

Year being reported:

2011

License No:  Issued Date:   
 Expiry Date:

Project Name:

Licensee:

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B  Item 2

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	<input type="text" value="Lakes"/>	
Water Quantity:	<input type="text" value="10/day"/>	Quantity Allowable Domestic (cu.m)
	<input type="text" value="1.52/day"/>	Actual Quantity Used Domestic (cu.m)
	<input type="text" value="173/day"/>	Quantity Allowable Drilling (cu.m)
	<input type="text" value="19.69/day"/>	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal  
☒ Sewage  
☒ Drill Waste  
☒ Greywater  
☐ Hazardous  
☒ Other:

Additional Details:

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

~1000 kg of Calcium Chloride on land/snow. Shovelled the product into bags and slung to the berm at Roche Bay for eventual removal from site. Followed up on Nov. 29, 2011 after sampling and testing resulted in a recommendation by an independent consultant of no further water quality monitoring being required.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

< 5 Gallons of Diesel on lake water. Used absorbent pads and booms to clean up the petroleum. Followed up on Nov. 29, 2011 after sampling and testing resulted in a recommendation by an independent consultant of no further water quality monitoring being required.

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Please refer to the attached Spill Contingency Plan

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

Please refer to the attached Abandonment and Restoration Plan

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Please refer to the attached A & R Plan and the 2011 Project Summary and 2012 Project Plans

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Not Applicable (N/A)

Additional Details:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Not Applicable (N/A)



Additional Details:

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



some comments arose that were addressed immediately on the inspection date or completed following the inspection and inspectors were notified.

**Any responses or follow-up actions on inspection/compliance reports**

Inspection and Compliance Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

INAC Land & Water Inspection conducted on July 12, 2011. During the inspection, some comments arose that were addressed immediately on the inspection date or completed following the inspection and inspectors were notified.

**Any additional comments or information for the Board to consider**

<b>Date Submitted:</b>	February, 2012						
<b>Submitted/Prepared by:</b>	Gary Williams						
<b>Contact Information:</b>	<table border="1"> <tr> <td><b>Tel:</b></td> <td>416-203-0057 ext. 224</td> </tr> <tr> <td><b>Fax:</b></td> <td>416-860-9900</td> </tr> <tr> <td><b>email:</b></td> <td><a href="mailto:gary@advanced-exploration.com">gary@advanced-exploration.com</a></td> </tr> </table>	<b>Tel:</b>	416-203-0057 ext. 224	<b>Fax:</b>	416-860-9900	<b>email:</b>	<a href="mailto:gary@advanced-exploration.com">gary@advanced-exploration.com</a>
<b>Tel:</b>	416-203-0057 ext. 224						
<b>Fax:</b>	416-860-9900						
<b>email:</b>	<a href="mailto:gary@advanced-exploration.com">gary@advanced-exploration.com</a>						

