

November 12<sup>th</sup>, 2025

Richard Dwyer  
Manager of Licensing  
Nunavut Water Board  
Gjoa Haven, NU X0B 0A3  
(867) 360-6338  
[richard.dwyer@nwb-oen.ca](mailto:richard.dwyer@nwb-oen.ca)

**RE: Water Licence 2BM-ULU2030 Compliance Assessment Status Report**

Water Licence 2BM-ULU2030 underwent a compliance assessment on November 12, 2025. The compliance assessment determined there were no non-compliant items identified. During a water licence inspection conducted on August 6, 2025, the inspector noted missing signage required by the water licence at the greywater discharge location. Rectifying actions placing appropriate signage at the location were taken prior to the date indicated on the inspection report. Please see the attached *251112 - Blue Star Water Licence 2BM-ULU2030 Compliance Assessment* for a complete list of items reviewed.

Please do not hesitate to contact me with any questions, concerns or for additional information.

Sincerely,

A handwritten signature in black ink, appearing to read "Tara Gunson".

Tara Gunson, B.Sc. P.Geo  
APEX Geoscience Ltd.  
[tgunson@apexgeoscience.com](mailto:tgunson@apexgeoscience.com)

CC: Darren Lindsay – Vice President Exploration – Blue Star Gold Corp.