



Suite 507-700 W. Pender Street,  
Vancouver, BC V6C 1G8  
CANADA  
Tel: +1.778.379.1433

02 June, 2025

Richard Dwyer  
Manager of Licencing  
Nunavut Water Board  
PO Box 119  
Gjoa Haven, NU  
X0B 1J0

Dear Mr. Dwyer,

**Re. 2BM-ULU2030 Part J Item 14 – Monthly Monitoring Program, APRIL 2025**

---

Further to Part J Item 14 of 2BM-ULU2030, Blue Star Gold Corp. (Blue Star) is pleased to provide the following in fulfillment of monthly monitoring requirements during periods of site activity. Activities commenced at Ulu Camp on April 1<sup>st</sup> which included camp operations and waste management. No sampling results are available for April 2025 for monitoring stations listed in Table 1 as none of the sites had flow to sample.

Table 1. Applicable monitoring stations, **APRIL 2025** (active site)

| Station ID   | Station Description                          | Comment                                       |
|--------------|--|---|
| ULU-1        | Water Intake at West Lake                    | See Table 2                                   |
| ULU-2        | Sewage effluent discharge point              | Inactive, facility decommissioned             |
| ULU-3        | Sewage effluent discharge point              | Inactive, facility decommissioned             |
| ULU-4        | Mine water pumped from underground Mine Sump | No underground operations. Not discharging    |
| ULU-4b       | Portal Surface Retention Pond                | Frozen  |
| ULU-5        | Settling/Neutralization Pond                 | Pond not constructed                          |
| ULU-6        | Settling/Neutralization Pond                 | Pond not constructed                          |
| ULU-7        | Runoff from Waste Rock Pile                  | Not flowing.                                  |
| ULU-8        | Runoff from Ore Pad                          | Not flowing.                                  |
| ULU-9        | Outflow from East Lake                       | Not flowing.                                  |
| ULU-10       | Ulu Lake Inflow from East Lake               | Decommissioned                                |
| ULU-11       | Ulu Lake Outflow                             | Not flowing.                                  |
| ULU-12       | Domestic water intake for new camp           | New camp not constructed                      |
| ULU-13       | Soil treatment facility water holding pond   | Pond not constructed                          |
| ULU-14       | Airstrip Bulk Fuel Storage Facility          | Not yet constructed for the season            |
| ULU-15       | Landfill Facility                            | Not flowing.                                  |
| MW-1, -2, -3 | Monitoring well at soil treatment facility   | Facility not constructed; wells not installed |

Table 2. ULU-1 Daily volume, **APRIL 2025** (domestic and drilling water use).

| Date   | Volume (m <sup>3</sup> ) |          |               |       |
|--|--------------------------|----------|---------------|-------|
|  | Domestic                 | Drilling | Core cutting* | Total |
| 1  | 0                        | -        | -             | 0     |
| 2  | 0                        | -        | -             | 0     |
| 3  | 0.997                    | -        | -             | 0.997 |
| 4  | 0                        | -        | -             | 0     |
| 5  | 0                        | -        | -             | 0     |
| 6  | 1.632                    | -        | -             | 1.632 |
| 7  | 0                        | -        | -             | 0     |
| 8  | 0                        | -        | -             | 0     |
| 9  | 2.057                    | -        | -             | 2.057 |
| 10   | 0                        | -        | -             | 0     |
| 11   | 0                        | -        | -             | 0     |
| 12   | 0                        | -        | -             | 0     |
| 13   | 4.224                    | -        | -             | 4.224 |
| 14   | 0                        | -        | -             | 0     |
| 15   | 1.701                    | -        | -             | 1.701 |
| 16   | 0                        | -        | -             | 0     |
| 17   | 3.679                    | -        | -             | 3.679 |
| 18   | 3.245                    | -        | -             | 3.245 |
| 19   | 3.787                    | -        | -             | 3.787 |
| 20   | 3.902                    | -        | -             | 3.902 |
| 21   | 3.343                    | -        | -             | 3.343 |
| 22   | 3.786                    | -        | -             | 3.786 |
| 23   | 4.201                    | -        | -             | 4.201 |
| 24   | 3.838                    | -        | -             | 3.838 |
| 25   | 3.672                    | -        | -             | 3.672 |
| 26   | 3.664                    | -        | -             | 3.664 |
| 27   | 3.821                    | -        | -             | 3.821 |
| 28   | 3.842                    | -        | -             | 3.842 |
| 29   | 3.39                     | -        | -             | 3.39  |
| 30   | 4.233                    | -        | -             | 4.233 |
| *core cutting water is included in the domestic extraction |                          |          |               |       |

If you have any questions or concerns about this report, please don't hesitate to reach out.

Kindest regards,

Annabelle Perry

Environmental Technician

Blue Star Gold Corp.

enviro@bluestargold.ca

778-379-1433

cc. T. Bolt, Kitikmeot Inuit Association  
J. Bolt, Crown-Indigenous Relations and Northern Affairs Canada  
D. Lindsay, Blue Star Gold Corp