



DIAND Nunavut District
Box 100
Iqaluit, NT
XOA OHO

Your file Votre référence

Our file Notre référence

September 22, 1997

B9545-5-N6L1-1642


Mr. Don St. John, President
Eskimo Point Lumber Supply and
Airport Services Ltd.
Arviat, NT
XOA OHO

Inspection Report - Water Licence N6L1-1642
Hydrostatic Testing - Arviat, NT.

1. By copy of this letter, the Nunavut Water Board is advised that an inspection was carried out on August 7, 1997 at the Arviat tank farm in order to determine whether all restoration work was completed in accordance with water licence N6L1-1642.
2. The area was found to be restored to a degree to which it was not possible to tell that such work had been undertaken in the first place.
3. It is my recommendation that this file be closed and that Eskimo Point Lumber Supply has met the terms and conditions of the licence.

Sincerely,

Paul Smith
Water Resources Officer
Nunavut District



- cc. - Nunavut Water Board, Gjoa Haven
- DIAND Water Resources, YK
- RMO, DIAND, Rankin Inlet