



N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line
24-Hr. Spill Line: 867-886-2200
Phone: 867-886-2200-8130
Fax: 867-886-2200-8924

A Report date and time FEB 6/2001 4:00 PM		B Date and time of spill (if known) FEB 6/2001 10:30 AM		C Original report Update no. 01-02 9	
D Location and map coordinates (if known) and direction (if moving) CHESTERFIELD INLET, NUNAVUT					
E Party responsible for spill HARLET OF CHESTERFIELD INLET					
F Product(s) spilled and estimated quantities (provide metric volume/weight if possible) HEATING FUEL, APPROXIMATELY 2000 LITRES					
G Cause of spill WATER TRUCK ACCIDENTALLY HIT FUEL TANK STAND					
H Is spill contained? ☒ yes ☐ no		I If spill is continuing, give estimated rate no		J Is further spillage possible? ☐ yes ☒ no	
K Extent of contaminated area (in square metres if possible) 40 FT X 30 FT					
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) SNOW COVER, PERMIFROST GROUND				M Containment method (dikes, berms, etc.) NONE	
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials ALL SNOW AT THE SPILL SITE WAS TAKEN TO THE DUMP. FLOOR DRY (SILICA SAND) 100 LBS WAS SPREAD ONTO THE CONTAMINATED AREA.					
O Do you require assistance? ☒ yes ☐ no		P Possible hazards to person, property, or environment, eg: fire, drinking water, fish or wildlife NONE			
Q Comments and/or recommendations DURING THE SUMMER MONTHS THE REMAINING CONTAMINATED GROUND CAN BE REMOVED. ABSORBMENT MATERIAL (ROLLS) WAS LAID OVER CONTAMINATED AREA. ONGOING MONITORING WILL TAKE PLACE, ADDING NEW ABSORBMENT MATERIAL WHEN, AND AS REQUIRED.					
Reported by DARREN RITTER		Position, Employer, Location SENIOR ADMINISTRATIVE OFFICER, MUNICIPALITY CHESTERFIELD INLET		Telephone (867) 898-9951	
Reported to ALAN CHOUHARD		Position, Employer, Location ENV. PROTECTION OFFICER, GOVY OF NUNAVUT ARVIAT		Telephone (867) 857-2828	

MMT 1752/220