

2/3

<u>Community / Licen</u>	<u>Date of Inspection</u>	<u>Lab Number</u>	<u>Remarks</u>
Arctic Bay (Adams Creek) B9545-5-A11	10/7/87	870610	① Clarify identification of Adams Creek as site location of sampling in July 87 vice Marcil Lake 2. Provide assessment of water acceptability under Cdn. standards
Iqaluit B9545-5- N5L4-0087	2/7/87	870531	1. Provide assessment of water acceptability under Cdn. standards
Nanisivik Mines B9546-7- N5L3-0159	11/7/87	870677 870678 870679 870680 870681 870682 870683 870684 870685 870686 870687	1. Provide assessment of water acceptability under license outline
Broughton Island B9545-5- N4L4-0640	11/8/87	874031	1. Provide assessment of water acceptability under Cdn. standards
Wall Beach B9545-5-H6	19/8/87	87031	1. Provide assessment of water acceptability under Cdn. standards
Igloolik B9545-5- N4L4-0571	17/8/87	871032 871033	1. Provide assessment of water acceptability under Cdn. standards
Hamlet of Resolute Bay B9545-5- N4A4-0427	8/7/87	870545	1. Provide assessment of water acceptability under Cdn. standards
Resolute Bay DOT B9545-5- N5A4-0110	?? 21/11/86 5/5/87 19/7/86 20/8/86 12/2/86 22/12/86 22/1/87	60731 60763 870145 60433 60573 60684 60788 70036	1. Last recorded inspection report on file dated 18 April 86 (Madill) 2. Review of file did not identify specific requirement for most of these samplings activities - can you explain 3. Provide assessment of water acceptability under Cdn. standards 4. Was DOT location inspected during visit to Resolute Bay - summer 87?

3/3

Pangnirtung  
9545-S-  
NSL4-1447

1. H. Madill in Pangnirtung 8-9  
August 87 - please advise if inspect.  
and / or water sampling was  
undertaken at that time (last formal  
inspection on record is shown as  
June 85 - P Bannon)