



Canada NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130 FAX: (867) 873-6924 EMAIL: spills@gov.nt.ca

										REPORT LINE USE ONLY		
Α	REPORT DATE: MONTH – DAY – YEAR 06-03-2010			REPORT TIME 11:00		☑ ORIGINAL SPILL REPORT, OR			ORT, OR	REP	ORT NUMBER	
В	OCCURRENCE DATE: MONTH – DAY – YEAR Sometime in May 2010			OCCURRENCE TIME		☐ UPDATE# TO THE ORIGINAL SPILL			REPORT			
С	LAND USE PERMIT NUMBER (IF APPLICABLE)			·	WATER LICENCE NUMBER (IF APPLICABLE)							
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FRO Arctic Winter Games Facility Iqaluit, NU.			OM THE NAMED LOCATION			REGION ☐ NWT ☑ NUNAVUT ☐ ADJACENT JURISDICTION OR					
Е	LATITUDE DEGREES MINUTES SECONDS			LONGITUDE DEGREES MINU			ITES SECONDS					
F	RESPONSIBLE PARTY OR VESSEL NAME City of laaluit			RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION PO. Box 460 Igaluit. NU. XOA 0H0								
G	ANY CONTRACTOR INT		CONTRACTOR ADDRESS OR OFFICE LOCATION n/a									
Н	PRODUCT SPILLED Heating Fuel			QUANTITY IN LITRES, KILOGRAMS OR CUBIC Mapprox. 20 litres			IBIC MET	TRES	RES U.N. NUMBER			
	SECOND PRODUCT SPILLED (IF APPLICABLE none		,	QUANTITY IN LITRES, KILOGRAMS OR CU			BIC MET	METRES U.N. NUMBER				
I	SPILL SOURCE Heating fuel tank		-	SPILL CAUSE Heat expansion caused overfloor			,	AREA OF CONTAMINATION IN SQUARE METRES 24 ft2				
J	FACTORS AFFECTING SPILL OR RECOVERY frozen ground		no DES	Y ASSISTANCE REQUIRED			HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT none					
K	observing, we found that when the fuel tank was last filled there was not enough room left for expansion should the weather warm up. The fuel in the tank expanded in the warm weather, and approximately 20 litres leaked out of the fuel gauge on the top of the fuel tank on to the ground immediately under the tank. City employees used shovels to clean up contaminated soil under the tank, and got as much as they could until the ground thawed more. On June 03, 2010 another attempt to clean up the remaining contaminated soil was done. The remaining contaminated soil was removed and taken to a contained disposal site. We are now waiting for permission to backfill the site upon approval from Envirment and Oceans and Fisheries. Approximately 1.5 cubic meters of soil were removed. Upon approval, site will be backfilled with gravel, or excavate more material if required.											
L	REPORTED TO SPILL LINE BY Frank Ford				MPLOYER Citv of Iaaluit	LOCATIO Idaluit.		ION CALLING FROM t. NU.			TELEPHONE 867-979-5653	
М	ANY ALTERNATE CONTACT Rob Hogan		POSITION Utilidor Forman		MPLOYER City of Igaluit			TERNATE CONTACT LOCATION aluit, NU		ΓΙΟΝ	ALTERNATE TELEPHONE 867-222-2941	
REPOR	T LINE USE ONLY											
N	RECEIVED AT SPILL LINE BY		POSITION Station operator		EMPLOYER		LOCATION CALLE				REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY ☐ EC ☐ CCG ☐ GNWT ☐ GN ☐			ILA INAC NEB TC SI		IGNIFICANCE MINOR MAJO] Majof	FILE ST CLOSE			TATUS ☐ OPEN ☐ ED	
AGENCY		CONTACT NAME		C	CONTACT TIME REMA		REMAR	IARKS				
LEAD AGENCY												
FIRST SUPPORT AGENCY												
SECOND SUPPORT AGENCY												
THIRD SUPPORT AGENCY												