

INAC, Nunavut District P.O. Box 100 Building 918 Iqaluit, NU, XOA 0H0

Submitted Via E-Mail
Our File: Unlicensed (3BM-RUT)
Your File:
CIDM # 374110

December 15, 2009

Don Carr Technical Advisor NUNAVUTWATER BOARD P.O. BOX 119 GJOA HAVEN, NU X0B 1J0

TEL: (867) 360-6338 FAX: (867) 360-6369

RE: Response to the Nunavut Water on the Location of the Utilidor Outfall

Mr. Carr,

On December 1st, 2009 we spoke briefly regarding the location of the Resolute Bay Utilidor outfall location. During that conversation I had advised you after reviewing the e-mail correspondence contained within the Nunavut Water Boards FTP site it was noted that there appeared to be some confusion over the location of the outfall.

Subsequently I provided you four pictures in an e-mail collected during past inspections. This was to provide you and the Nunavut Water Board some context to the discussion and to assist the Board in making a determination on the issue.

I hope the information provided assists the board in their determination.

Sincerely,

Andrew Keim Water Resources Officer Field Operations Unit Indian and Northern Affairs Canada Box 100 Building 918 Iqaluit, Nunavut XOA OHO Ph: 1-867-975-4298

Fx: 1-867-975-6445 Andrew.Keim@inac.gc.ca

CC:

Peter Kusugak – INAC Bernie MacIsaac- INAC