




WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
David Burgess Geological Survey of Canada Canada Center for Remote Sensing 588 Booth Street Ottawa, ON K1A 0Y7 Email: david.burgess@nrcan.gc.ca		None Present	
Licence No. / Expiry		Representative's Title	
3BC-MBA0919 EXP. 31/03/19			
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
05/07/2014		A. Keim	
Activities Inspected			
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage			
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Discharge <input checked="" type="checkbox"/> Other:			

Conditions:		A - Acceptable		C - Concern		U - Unacceptable		NA – Not Applicable		NI – Not Inspected	
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NI			Water Management Structures	NA			Storage	NA		
Flow Measure. Device	NI			Culverts / Bridges	NA			Spills	NA		
Source:				Drainage	NA			Spill Plan	NA		
Water Use:	NI			Erosion / Sediment	NA						
Recirculation (y /n)	N			Mitigation Measures	NA			Administrative			
				Reclamation Activities	NA			Records	NI		
				Materials Storage	NA			Reports	C		3
Waste Disposal				Signage	NA			Plans	A		
Waste Water	NA							Notifications			
Solid Waste	NA			Monitoring				Other			
Hazardous Waste	NA			Sample Collection / Analysis	NA			Grise fiord			1
								Devon Ice cap			2
<i>*The number in the comments field will correspond with specific comments provided below.</i>											
Samples taken by Inspector:				Location(s):							
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
<p>On July 6th the Inspector attended the location listed in the 2009 Application as location associated with the Grise Fiord Glacier to conduct an inspection of the site as one of the constituent locations covered under the 3BC-MBA0919 Project. Upon arrival at the general location the inspector noted that no evidence of occupation or disturbance could be seen. No persons, structures or activities could be seen in the area. The site was found in what appeared to be a natural state with no evidence of disturbance.</p> <p>On July 9th the Inspector attempted to attend the areas around the sites listed in the 2009 application submitted to the Nunavut Water Board as located on the Devon Ice cap. Poor weather including flat light and a low ceiling prevented the Inspector from attending these sites to conduct the required Inspection.</p>			
SECTION 2	<input checked="" type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
<p>The Licensee is in contravention of the following provision of the issued license 3BC-MBA0919, specifically Part B item 1.</p> <p>The Licensee shall file an Annual Report on the appurtenant undertaking with the Board no later than March 31st of the year following the calendar year being reported, containing the following information:</p> <ul style="list-style-type: none">a. A summary report of water use activities;b. A list of unauthorized discharges and a summary of follow-up actions taken;c. A description of all progressive and or final reclamation work undertaken, including photographic records of site conditions before, during and after completion of operations;d. A summary of all information requested and results of the Monitoring Program; ande. Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.			



Aboriginal Affairs and
Northern Development Canada

Affaires autochtones et
Développement du Nord Canada

SECTION 3	<input checked="" type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.____)	<input checked="" type="checkbox"/> Action Required (s.____)
<p>A review of the Nunavut Water Board web site (FTP site) cannot locate an Annual Report for 2013 for the above noted Project. The Licensee has 30 days from receipt of this report to file the required Annual Report. If an annual report has been filed the Proponent is reminded that it is the responsibility of the Licensee to ensure that all submissions to the Board are acknowledged by the licensing department.</p> <p>Failure to file an Annual Report within the 30 day deadline may result in further enforcement action has allowed under the Nunavut Waters and Nunavut Surface Rights Tribunal Act</p>			

Photo Log			
Date	Authorization	Camera	Inspector
July 6, 2014	3BC-MBA0919	Sony Cyber shot	A. Keim



Figure 1 July 6 2014 Top facing south of the Grise Fiord Glacier North of Grise Fiord



Figure 2 July 6 2014 Glacial extent in valley west of the Community



Figure 3 Location Listed in 3BC-MBA License for the Grise Fiord Glacier



Figure 4 July 9th, Poor weather on Devon Ice Cap. Too dangerous to continue

Licensee or Representative	Inspector's Name
	A.Keim
Signature	Signature
	-Sent by Email- Original on file
Date	Date
	September 8, 2014

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---