

24-Hour Report Line



NUNAVUT SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-Hour Report Line
Phone/Fax (867) 857-8130
Fax (867) 857-6924

A Report Date and Time MAY 17, 02		B Date and Time of Spill (if known) JAN 02		C Original Report Update No. 1		Spill Number 02-024	
D Location and Map Coordinates (if known) and Direction (if known) ARVUT NORTHERN STAGE							
E Party Responsible for Spill (Full Name and Address) if known (add other parties)							
F Product(s) Spilled and Estimated Quantities (provide metric volume/weights if possible) if not known, state tank's contents (if known) FUEL OIL							
G Cause of Spill if known							
H Is Spill Terminated? ☐ Yes ☐ No		I If Spill is Continuing, give Estimated Rate if known, state tank's contents (if known) ☐ Yes ☐ No		J Is Further Spillage Possible? ☐ Yes ☐ No		K Extent of Contaminated Area (in square metres if possible) if known, state tank's contents (if known) BRD EXT.	
L Factors Affecting Spill or Recovery (weather conditions, terrain, snow cover, etc.) if known, state tank's contents (if known)				M Containment (containment depression, dikes, etc.) if known, state tank's contents (if known)			
N Action, if any, taken or proposed to Contain, Recover, Clean up or Dispose of Product(s) and Contaminated Materials if known, state tank's contents (if known)							
O Do You Require Assistance? ☐ No ☐ Yes describe if known, state tank's contents (if known)				P Possible Hazards to Persons, Property or Environment e.g. fire, drinking water, fish or wildlife if known, state tank's contents (if known)			
Q Comments and/or Recommendations Recommendations: The wall surrounding the two fuel tanks should be heightened to approximately one meter. The fresh water distribution pipes (for delivery of potable water, and the overflow pipe) should be slightly relocated far away from this area, since, in winter, the water from the overflow pipe goes directly inside the barn and freeze, leaving no room for potential fuel overflowing from the tanks. PLUS THE GROUND SHALL BE INSPECTED							
Reported By A. CHAMBERLAIN				Position, Employer, Location E.P.O. KIVUKI			
Reported To P.E. CHAMBERLAIN				Telephone 867 857 2888			