
Your file Votre référence

Our file Notre référence

B9545-5-N6L3-1191

DIAND Nunavut District Box 100 Iqaluit, NT XOA OHO

August 26, 1997



Mr. Dennis Zettler Senior Administrative Officer Hamlet of Baker Lake Baker Lake, NT XOC OAO

Dear Mr. Zettler;

Water Licence Inspection - August 6, 1997

- 1. Attached is a copy of the inspection report prepared as a result of the water licence inspection of August 6, 1997.
- 2. There are a number of issues that must be addressed. Primarily is the requirement for the 1996 Annual Report to be submitted per Part B, Item 1 of water licence N6L3-1191. In addition, warning signs must also be posted per Part B, Item 4 of the licence. Lastly, SNP Station signs must be posted at the water supply and waste disposal per Part B, Item 6 and SNP, Part A of the licence.
- 3. This last requirement is dependent on the recommendations made in a study to determine the best location for this SNP station. The final decision of where to locate this station rests with the Nunavut Water Board. By copy of this letter, the Board and Water Resources Division, DIAND, YK, are requested to conclude this study and finalize the location of this SNP station.
- 4. Once this has been done, there are sampling requirements that the Hamlet will have to undertake to comply with the licence. Until this SNP station is determined, the Hamlet is not being required to collect SNP samples.
- 5. Another issue that must be addressed by the Board is the matter of the O+M plan that was submitted in November of 1996. This is a well developed plan that awaits approval by the Board.

- 6. Work is continuing on cleaning up an abandoned waste disposal site near Airplane Lake. If not already done so, the Hamlet should provide a copy of the clean-up plan to the Nunavut Water Board.
- 7. Results of water samples collected during the inspection will be forwarded once all analysis has been completed.
- 8. If you have any questions about the inspection report or other matters noted above, please do not hesitate to contact this office at your convenience.

Sincerely,

Paul Smith

Water Resources Officer

Nunavut District

cc. - Nunavut Water Board, Gjoa Haven

- Water Resources Division, DIAND, YK
- RMO, DIAND, Rankin Inlet
- MACA, Rankin Inlet (Don Forsyth)
- Public Health, Rankin Inlet (Leslie Moody)

MUNICIPAL WATER USE INSPECTION FORM

DATE: 6 August 97	_ COMPANY REP: Lugh Those - Foreman
LICENSEE: Hamlet of Baker Lake	- COMPANY REP: thy h lkse - Forema
WATER SUPPLY	LICENCE #: N(eL 3-1141
Owner/Operator: Hamlet	Quantity Used (to date): ~ 30,300 m 3/40
Intake Facilities: Not i started Started	
Flow Meas_Device A Convey Lines NA	Chem. Storage N
Comments As noted last year	
advanced age. Finding has been lines.	en Secured to 12 places are of
	- Place in Take
WASTE DISPOSAL	
Sewage Sewage Treatment System (primary, secon	dary or tertiary) Primary # +
Natural Water body Note 2 Co	ntinuous Discharge (land or water) to Land
Seasonal Discharge We	etlands Treatment Trench
Solid Waste: Owner/Operator: Hamlet	
Landfill Burn & Landfill	Other
Indicate: A Acceptable U Unacceptable N/A - N Disch. Quality Samples (client at Decant Structure)	ot Applicable
Disch Mark 3 Decam Structure	N/A Erosion Mill Note 4
Domo Duting	Seepages N/A
Canadanai	N/A Spills note 6
Poriodo of Division Color	Tarrian
Comments: Note 2 - Sewage 13 chi3 pose	Rate: Vanies
Flows down a heavily reactated of	acto
through a wetlando area to ano	He so I want pond Figure
Arplane lake and evastually	to Robert I be again to
FUEL STORAGE Owner: Or	perator Condition of Tanks
Berms & Liners Water within berm:	Evidence of Leaks:
Pump Station and Cate	chment Berm
Pipeline Condition Not Applicable:	t inspected.
'RVEILLANCE NETWORK PROGRAM	
Samples Collected: (Hamlet) See	
(DIAND) 1191-1, 119	
Signs Posted: SNP not posted	Warning Required
Record & Reporting 1996 Annual Repo	rt has not been submitted
Geotechnical Inspection:	
Non-Compliance of Act or Licence: 1996 A.	annual Report has not been
lacitity Said at 7	
Jacitity. SNP station signs at 1191-2 (When officially identit	
- Contrady Identil	n'ed).
	Page 2 attached Yes No
Licensee Representatives Title	- taul Smith
NA	Inspectors Name
Licensee Representatives Signature	tam Inon
· ·	Inspectors Signature

WHITE COPY - Inspector's File YELLOW COPY - Licensee GREEN COPY - Field Rep

PINK COPY - Water Resources

WATER USE INSPECTION REPORT (continued)

Date: 6 August 97
Licence #: N&L3-119
General Comments: (Continued)
Note 3 A water sample was gollected & the inlet to
Board. Consea the He II I have not been officially approved by the
Board. Consequently, the Hamlet has not collected any
Samples because the class it is not collected any
Samples because the clause that orthogo Sampling regularing
is dependent on the SUP location being made official.
Note of A Channel has been out through the tetentron
bern at the sewage disposed area.
Note 5. The Hamlet prepared an O+M plan for their waste
of 1996. The Board has yet to approve of the plan.
Note 6 There is a waste oil storage area/pit at the
Waste disposal site. Waste o'l is no longer placed here
as there is a waste oil furnace now operating privately.
The pit is heard set to make now operating privately.
be done at the Waste disposal area.
Note 7 - The second sec
we an abandoned unit has been busy working on cleaning
Board with detailed plans of their clean-up.
General - The Hamlet has taken over services provided by DPW & S.
The state of the s
Spring time). (especially at
$\mathcal{L}_{\mathcal{L}}$
Water Inspector
1 **

