



WATER LICENCE INSPECTION FORM

Original
 Follow-Up Report

Licensee Hamlet of Baker Lake	Licensee Representative Clayton Croucher
Licence No. / Expiry 3BM-BAK1526	Representative's Title Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations --
Date of Inspection August 1 st 2017	Inspector Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input checked="" type="checkbox"/> Other: Municipal <input type="checkbox"/> Other: Hazardous waste	

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input type="checkbox"/> Non-Compliance with Act or Licence (s.____)	<input type="checkbox"/> Action Required (s.____)
<i>Summary</i>			
On August 1 st , 2017 Indigenous and Northern Affairs Canada's Water Resource Officer, Atuat Shouldice completed an annual Community inspection of the hamlet of Baker Lake permit 3BM-BAK1526. The inspection was conducted with Megan Lusty, Municipal Planning Engineer with the Government of Nunavut.			

SECTION 2	<input type="checkbox"/> Comments (s.____)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s.____)
<i>Observations</i>			
<i>Water use</i>			
Facilities related to water use were inspected during this site visit. The freshwater pumphouse was in good order and records were available for review.			
<i>Landfill</i>			
During the inspection the hamlet was burning domestic waste; the hamlet is reminded that any burning occurring onsite must be done in a manner that prevents waste from entering freshwater. The landfill lacked housekeeping in relation to waste oil drums. Although no waste oil was observed entering water, the hamlet is encouraged to put some order in the manner waste oil is currently being managed.			
<i>Hazardous waste</i>			
Batteries, empty propane tanks and used tires are stored at a separate site in seacans waiting to be shipped out. Multiple seacans are filled with these items and batteries are stored in lined mega bags to prevent leaching of waste in to the environment. No waste was observed entering the environment.			
<i>Sewage</i>			
The hamlet of Baker lake has conducted repairs to the sewage lagoon holding cell in order to increase contact time and the unauthorized release of waste water.			

SECTION 3	<input type="checkbox"/> Comments (s.____)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s.____)	<input checked="" type="checkbox"/> Action Required (s.3)
The inspector requests that more attention be given to the storage of waste oil before the next inspection season of 2018. The drums should be capped to ensure oil does not leach into the environment.			

Licensee or Representative	Inspector's Name WRO A Shouldice
Signature	Signature
Date	Date 4/19/2018

Office Use Only: Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---

cc. Erik Allain, Manager Field Operations, INAC