

WATER LICENCE INSPECTION FORM

Original Follow-Up Report

Action Required (s.

Licensee			Licensee Representative				
Hamlet of Chesterfiel	d Inlet		Roy Mullins				
Licence No. / Expiry	41.		Representative's Ti				
3BM-CHE1523/ May 14 th , 2023			Senior Administrative Officer				
Land / Other Authorization	ns		Land / Other Authorizations				
Data of last and last							
Date of Inspection August 17 th 2018			Inspector Atuat Shouldice				
			Atuat Shouldice	:			
Activities Inspected Camp	☐ Drilling	Mining	☐ Constructio	n \square Rec	clamation	☐ Fuel Storage	
Roads/Hauling	<u> </u>	and Water Treatment Facility	Other: Land				
Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspe	ected NA-	Not applicable	
PART:		-		Item No.*	Condition	Observation No.*	
A: SCOPE, DEFINITIONS AND ENFORCEMENT							
B: GENERAL CONDITIONS			1,5,6	A,C,A	1,2,3		
C: CONDITIONS APPLYING TO WATER USE			1,2,5	A,A,A	4,5,6		
D: CONDITIONS APPLYING TO WASTE DISPOSAL				4,4,7	A,A,A	7,8,9	
E: CONDITIONS APPLYING TO MODIFICATIONS AND CONSTRUCTION							
F: CONDITIONS APPLYING TO OPERATION AND MAINTENANCE							
G: CONDITIONS APPLYING TO ABANDONMENT AND RECLAMATION							
H: CONDITIONS APPLYING TO MONITORING PROGRAM			1	A	10		
*The item number	corresponds with sp	ecific conditions withir	n the licence and	the observation	number correst	oonds with specific	
		comments	provided below.				
		Location(s): CHE-4, F	Final Discharge f	or Effluent for th	ne wet land treat	tment area prior to	
Samples taken by Ins	pector:	the Finger Bay.					

RΔ	CK	CP	ΛI	IN	n

The Hamlet of Chesterfield Inlet is in the Kivalliq Region of Nunavut, located approximately 101 km Northeast of Rankin Inlet

Non-Compliance with Act or Licence (s.,

Inspector's Statement

On August 17th, 2018, a water licence inspection was conducted of water licence no. 3BM-CHE1523, issued to the Hamlet of Chesterfield Inlet. Roy Mullins, Senior Administrative Officer assisted with the inspection.

Observation

- 1. The Annual report is available for review on the Nunavut Water Board's FTP website.
- 2. A flow meter has been installed at the fresh water intake, Puigsuk Lake. The flow was broken at the time of inspection.
- 3. Appropriate signage is observed at the monitoring stations, as required by PART B item 6.
- 4. Water is drawn from Puiqsuk Lake using a conveyance line to the water reservoir.
- 5. The conveyance line from Puiqsuk Lake to the water reservoir is in need of repair; there are a number of holes in the line which causes water lose from the source to the reservoir. New pipe is to arrive on this season's barge.
- 6. The fresh water intake is equip with a screen.

Comments (s._1_)

- 7. The Sewage Disposal Facility ('SDF') has two sewage truck drop-off locations. The Hamlet predominately uses the new drop off location but, on an emergency basis, has had to use the old location because of back spray during bad weather events.
- 8. Sludge was removed from the settling pond of the SDF this year. The sludge was disposed of in an area designated for sludge in the Solid Waste Disposal Facility ('SWDF').
- 9. The Hamlet is segregating waste in the SWDF. Hazardous waste (e.g.: batteries and waste oil) is being placed into seacan with the intention to ship south for treatment. The Hamlet is currently looking for funding to complete this activity.
- 10. Samples have been collected by the inspector at monitoring station no. CHE-4. This is the final discharge point for effluent from the SDF. The inspector noted compliance with the quality limits prescribed in PART D item 4.



Report #2018-KIV06-AS Page 1 of 2

Relations Couronne-Autochtones et Affaires du Nord Canada

SECTION 2	Comments	Non-Complia	nce with Act or Licence	Action Required		
Concerns related to Water Licence no. 3BM-CHE1523;						
PART B Item 5: Failu	PART B Item 5: Failure to maintain a flow meter for measuring water volumes as required under Part H Item 1.					
 The licensee shall install a flow meter at the water intake before the period of the next inspection. 						
— The licensee is required to maintain a flow meter at the water intake in accordance with the conditions of this licence and						
s.11 of the	Nunavut Waters and Nunavu	ut Surface Rights T	ribunal Act.			
SECTION 3	Comments	Non-Complia	nce with Act or Licence	Action Required		
The Hamlet has made great changes to the management of the Solid Waste Disposal Facility in 2018. The Hamlet is reminded that						
fresh water must be metered from the source to ensure that all water use is correctly recorded.						
The Inspector was satisfied with the work completed this year at the Solid Waste Disposal Facility.						
Licensee or Representati	ve		Inspector's Name			

Licensee or Representative	Inspector's Name
Roy Mullins	Atuat Shouldice
Signature	Signature
	Sent Electronically
Date	Date
	February 12th, 2018

CC: Licensing Department, NWB

Justin Hack, Manager of Field Operations, CIRNAC Megan Lusty, Municipal Works, CGS



Report #2018-KIV06-AS Page 2 of 2