



February 22, 2013

 (867) 899-7301 (867) 899-7330



If this unauthorized discharge is foreseeable, the following sampling and testing procedure should be followed using GPS coordinates:

Please make sure that this is in addition to your extended annual sampling and testing program.