



WATER LICENCE INSPECTION FORM

☐ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Repulse Bay	Clayton Croucher
Licence No. / Expiry	Representative's Title
3MB-REP1520	Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations
Date of Inspection	Inspector
24/08/2015	Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
<input checked="" type="checkbox"/> Other: Deposit of waste	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Other: Water use
	<input checked="" type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA - Not Applicable	NI - Not Inspected
Water Use	Condition	Comment	Site Conditions	Condition	Comment
Intake/Screen	A		Water Management Structures	A	
Flow Measure. Device	A		Culverts / Bridges	A	
Source:	A		Drainage	A	
Water Use:	A		Erosion / Sediment	A	
Recirculation (y /n)	Y		Mitigation Measures	A	
			Reclamation Activities	C	1
			Materials Storage	A	
			Signage	A	
Waste Disposal					
Waste Water	A				
Solid Waste	A		Monitoring		
Hazardous Waste	A		Sample Collection / Analysis	A	
*The number in the comments field will correspond with specific comments provided below.					
Samples taken by Inspector:	Location(s): Repulse Bay				
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
A compliance inspection was conducted on August 24 th 2015 of water licence 3BM-REP1520.			
SECTION 2	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
Reclamation Activities: A new land fill has been developed for the Hamlet and all waste should now be sent to this facility. Any uncapped waste still remaining at the old land fill should be relocated to the new land fill and recapped.			
Storage: Waste oil drums were requested by the inspector to be capped and palletised in order to prevent the spread of contaminants. (Action Item 1)			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s. __)
The Hamlet of Repulse Bay has started following the yearly goal of the Water licence working compliance group and is storing batteries in a seacan (shipping container) at the local landfill. Boxes are being built to store the batteries to ensure proper shipping and disposal.			
Action Item 1: Waste oil drums were requested by the inspector to be sealed and palletized to prevent the spread contaminants.			
The new Senior Administrative officer, Denis Doral, has advised me that all action item with be corrected before the next municipal inspection which will take place during the summer of 2016 at a date to be determined.			

Licensee or Representative	Inspector's Name
	Atuat Shouldice
Signature	Signature
Date	Date
	12/22/2015