

UNAVUT SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

24-hour Report Line 24-hour (867) 923-8130
 Phone/Telex (867) 923-8130
 Fax/Telex (867) 923-8130

24-hour Report Line 24-hour (867) 923-8130

Phone/Telex (867) 923-8130

Fax/Telex (867) 923-8130

A. Date and Time 01/11/02 1700		B. Date and Time of Spill (Approx.) 01/11/02 1700 (approx.)		C. Original Report Updated 01/11/02		D. Spill Number 02-251	
D. Location and Map Coordinates (if known) and Direction (if known)							
Pangnirtung, Oilstean Equipment lot							
E. Party Responsible for Spill (Full Name and Address)							
Pangnirtung Co-op, P.O. 404, Pangnirtung, Nunavut XOA ORO							
F. Product Spilled and Estimated Quantity (approximate weight or volume if possible)							
P-50, approximately 100 litres							
G. Cause of Spill							
International Delivery fuel truck Lic #: C3678N main pump gasket broken							
H. Is Spill Continuing? ☒ Yes ☐ No		I. Is Further Spillage Possible? ☐ Yes ☒ No		J. Amount of Contaminated Area (in square metres if possible) 12 x 4.9 m		K. Contaminant (natural degradation, dyes, etc.) None	
L. Factors Affecting Spill or Recovery (weather conditions, terrain, snow cover, etc.)							
main effected area Snow							
M. Action, if any, taken or Proposed to Contain, Recover, Clean up or Dispose of Product(s) and Contaminated Materials							
Stopped the leak and pump out tank into 14 drums of heating							
N. Do You Require Assistance? ☒ Yes ☐ No, describe:				O. Possible Hazards to Person, Property or Environment (e.g. fire, drinking water, fish or wildlife)			
None				None			
P. Comments and/or Recommendations							
The fuel truck was parked over night by the Oilstean Equipment shop over night and the driver didn't observe the drippings since the pump pump was under the leak. Next day, Co-op manager, Walter Morey noticed drippings for the day and found it leaking very badly. He put large gate that a container to stop the leak into the ground. The pump is being repaired, and I recommend that shut off valves be repair so that if the basket breaks again it would stop the leak. Spill pump with one speaker remaining in and some and two kinds of water-based were dumped to the community dumpsite.							
FOR SPILL LINE USE ONLY							
Lead Agency: GNW							
Local Agency Contact and Time: GNW: Robert ENH 04/08/02 13:30							
Is this file now closed? ☒ Yes ☐ No							
Reported By Walter Morey		Position, Employer, Location Manager, Co-op, Pangnirtung		Telephone (867) 473-8790		Spill Significance	
Reported To Saklissie Smellorapik		Position, Employer, Location Wildlife Officer, Pangnirtung		Telephone (867) 473-8437			