

అండారా ఓల్లికి అండారా స్ట్రింగ్ ఎగ్గిర్గారింగ్ Department of Community and Government Services

Nunalingni Kavamatkunnilu Pivikhaqautikkut Ministère des Services Communautaires et gouvernementaux

January 27,2020

Richard Dwyer
Manager of Licensing
Nunavut Water Board
P.O. Box 119, Gjoa Haven, NU X0B 1J0

Phone: (867) 360-6338, Ext. 27, Fax: (867) 360-6369

Email: Richard.dwyer@nwb-oen.ca : licensing@nwb-oen.ca

Sub: Construction of a new Intake line and connection with the existing WTFS at Pond Inlet, Baffin Region.

Dear Mr. Dwyer

I am writing you to confirm that the during replacement of the submersible pump from inside of the intake, it was stuck and could not be pulled out for more than a month. The entire intake system is now frozen and inactive. Water is being extracted directly from the Lake and manually chlorinated. This is of coarse a short term measure.

Exp consulting services Inc has been hired for immediate design to lay down a new Intake pipe line parallel to the existing one to reactivate the Water truck fill station for normal operation. The existing intake line will be abandoned and left there untouched.

Exp's proposed design is attached. The as -built drawings will be submitted once the construction is completed.

Please accept this letter as the notice of Modification of the Municipality of Pond inlet Water Licence # 3BM-PON 1520, Part E.



בּתְרֶיס לאַנְילְאַת בּיתּד לאַנְילְאָת Department of Community and Government Services
Nunalingni Kavamatkunnilu Pivikhaqautikkut
Ministère des Services Communautaires et gouvernementaux

Please review this notice and contact me if you have any question or comment.

Thanks.

Bhabesh Roy, M.A.Sc., P.Eng.

Municipal Planning Engineer
Community Government Services
Baffin Region, Government of Nunavut
P.O.Box 379, Pond Inlet, X0A 0S0
Ph-867 899 7314; cell 867 899 1345

Fax-867 899 7328

E-mail: <u>broy@gov.nu.ca</u>