

JUL-19-01 01:28P



N.W.T. SPILL REPORT

(Oil, Gas, Hazardous Chemicals or other Material)

24-Hour Report Line
 24-hr. Toll-free 1-800-661-2222
 Phone/TTY: (403) 920-8130
 Fax/TTY: (403) 873-6824

A Report date and time July 18, 2001		B Date and time of spill (if known) July 17/01		C Original report number 01-283	
D Location and map coordinates (if known) and direction (if moving) Sewage Lagoon					
E Party responsible for spill Hamlet of Pond Inlet					
F Product(s) spilled and estimated quantities (provide metric volume/weights if possible) Raw Sewage 500 litres estimate					
G Cause of spill Berm not stable					
H Is spill contained? ☐ yes ☒ no		I If spill is continuing, give estimated rate 1002 m estimate		K Extent of contaminated area (in square metres if possible) 1002 m estimate	
L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) The spilled sewage is being pumped back to the lagoon slowly.			M Containment method (dike, berm, etc.) Berm not stable		
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated material(s) The spilled sewage is being pumped back to the lagoon slowly.					
O Do you require assistance? ☐ no ☒ yes			P Possible hazards to persons, property, or environment (e.g., fire, drinking water, fish or wildlife) Possible hazard to environment		
Q Comments and/or recommendations The sewage lagoon is leaking underneath the berm, from North East to South West. We have made another berm, about 40-50 feet south, but that berm is leaking also. The leak is going faster after rainfall					
Reported by Mona Katsak		Position, Employer, Location Water & Sewer Clerk Pond Inlet		Telephone 867 899 8934	
Reported to Brian Johnson		Position, Employer, Location Spill Crew		Telephone 867 873-6924	

NW 1730050

87-19-01 12:35 TO: AAL STATION/SPILL LINE

FROM:

P81