



## NUNAVUT SPILL REPORT (Oil, Gas, Hazardous Chemicals or other Materials)

$\frac{d\lambda}{dt} = \frac{\partial \lambda}{\partial t} + \frac{\partial \lambda}{\partial x} \frac{dx}{dt}$

24-Hour Report Line 24-06 Ab'10-06 2006-06-06 2006-06-06 2006-06-06

Phone/تلفون (867)920-8130

Fax / فاكس (867) 873-6924

<b>A Report Date and Time</b> February 22, 2002 01:00am		<b>B Date and Time of Spill (if known)</b> February 16, 2002 Roughly 14:00hrs		<b>C</b> <input type="checkbox"/> Original Report <input checked="" type="checkbox"/> Update		<b>Spill Number</b> 02-124	
<b>D Location and Map Coordinates (if known) and Direction (if moving)</b> Fuel Tank Farm, Community of Qikiqtarjuaq, Nu.							
<b>E Party Responsible for Spill (Full Name and Address)</b> Lealie Enterprises Ltd. Lealie Mukiwuaq D.O. Box 88 Qikiqtarjuaq, Nunavut X0A 0R0							
<b>F Product(s) Spilled and Estimated Quantities (provide metric volumes/weights if possible)</b> Jet A-1 Amount: 2 1/2 Barrels (45gallon) was recovered, contractor estimated 3-45gallon barrels was lost, but there seemed to have been a lot more then what was report, considering snow coverage within the area, also considering the amount of contaminated snow that was removed from the area. An area measured from length to width was 15meters / 18meters.							
<b>G Cause of Spill</b> Human Error							
<b>H Is Spill Terminated?</b> <input checked="" type="checkbox"/> Yes/ <input type="checkbox"/> No/		<b>I If Spill is Continuing, give Estimated Rate</b> Spill has stopped.		<b>J Is Further Spillage Possible?</b> <input type="checkbox"/> Yes/ <input checked="" type="checkbox"/> No/		<b>K Extent of Contaminated Area (in square metres if possible)</b> 15meters / 18meters	
<b>L Factors Affecting Spill or Recovery (weather conditions, terrain, snow cover, etc.)</b> Non-serviced valves, cold temperature delayed shutting.				<b>M Containment (natural depression, dykes, etc.)</b> Large holding tank at the dump.			
<b>N Action, if any, taken or Proposed to Contain, Remove, Clean up or Dispose of Product(s) and Contaminated Materials</b> Spill has been contained and clean up has been completed.							
<b>O Do You Require Assistance?</b> <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes, describe:		<b>P Possible Hazards to Persons, Property or Environment e.g. fire, drinking water, fish or wildlife</b> None at this time					
<b>Q Comments and/or Recommendations</b> Very good effort was put in to having this site cleaned, the contractor hired two local individuals to give him a hand, removing the contaminated snow from the compound to where it could later be removed by the Hamlets Loader and delivered to the community dump where there is a holding tank in place. Follow up was completed February 25, 2002 @ 13: 10 and was completed @ 13:35. I James Noble Wildlife Officer II of Qikiqtarjuaq inspected the site and satisfied with the effort that was put to having the site cleaned.  Please note: that the spill area was also covered with absorbent pads, and fresh snow was put on top of the pads to collect remaining fuel that may have not been recovered and will be removed during mid spring when the temperature starts to warm up.				<b>FOR SPILL LINE USE ONLY</b> Lead Agency Spill Significance Lead Agency Contact and Time Is this file now closed?			
<b>Reported By</b> James Noble		<b>Position, Employer, Location</b> Wildlife Officer II		<b>Telephone</b> 1 867 927 8966			