



DIAND Nunavut District
Box 100
Iqaluit, NT
XOA OHO

Your file Votre référence

Our file Notre référence

August 8, 1996

B9545-5-N6L4-0779

Mr. Antonio Masone
Senior Administrative Officer
Hamlet of Rankin Inlet
Rankin Inlet, NT
XOE OGO

Dear Mr. Masone:

Water Results Analysis - July 2, 1996 Inspection
Water Licence - N6L4-0779

Ref: My letter to you dated July 8, 1996.

1. Attached for your information are the analytical results for the water sample that were collected during the July 2, 1996 Inspection.
2. The results for raw water (0779-1) are well within the Canadian Health and Welfare Drinking Water Guidelines for the parameters tested.
3. A water sample from SNP Station 0779-4 was tested for metals. These results show low metal levels in the leachate below the waste disposal site area.
4. Further to my letter of July 8, 1996, I remind you of the various requirements that the Hamlet of Rankin Inlet must meet and request an update on the various outstanding issues identified during the inspection.
5. This office also stands ready to provide advice and suggestions for the Operation and Maintenance plan that must be produced.

Sincerely,

Paul Smith
Water Resources Officer
Nunavut District

- cc. - Nunavut Water Board, Gjoa Haven
 - RMO, DIAND Keewatin, Rankin Inlet
 - Municipal Coordinator, DIAND Water Resources Division, YK