

WATER USE INSPECTION REPORT

Date: August 3, 2009	Licensee Rep. (Name/Title): None
Licensee: Municipality of Rankin Inlet	Licence No.: 3BM-RAN0207 Expired

WATER SUPPLY

Source(s): Nippisar Lake		Quantity used: Unknown	
Owner:/Operator: Government of Nunavut			
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected			
Intake Facilities: U	Storage Structure: A	Treatment Systems: A	Chemical Storage: A
Flow Meas. Device: U	Conveyance Lines: A	Pumping Stations: A	Screen : A

Comments: The Municipality’s Water License has expired. A new application has been submitted to the Nunavut Water Board. The Municipality does not provide water nor wastewater services in the community. The Government of Nunavut has an expired water license for these services.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Direct discharge to Marine Environ

Natural Water Body: No	Continuous Discharge (land or water): Ocean	
Seasonal Discharge: No	Wetlands Treatment: None	Trench: None

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: U	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: U	Dyke Inspection: NI	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: None
Construction: NI	O&M Plan: U (none submitted)	A&R Plan: U (None submitted)
Discharge: continuous	Effluent Discharge Rate: Unknown	

Comments: A representative of the GN was unavailable to provide access during the Inspection to the Facility.

Solid Waste: Municipal Land fill and Metals waste area

Owner/Operator: Municipality of Rankin Inlet

Landfill: Not segregated	Burn & Landfill: U	Other: Hazardous Mat. Area : U
--------------------------	--------------------	--------------------------------

Comments The Municipality operates the Solid Waste Management Area. The Old dump is scheduled for replacement. Abandonment and reclamation plans, Operations and maintenance plans, the 2008 annual report were noted as having been submitted with the Application for renewal currently out for comment. The S.W.M. A continues to be unregulated by the municipality. The Area is un-segregated and contains hazardous materials as well as municipal wastes. The Licensee has failed to adhere to the issued Direction from 2008. These are the same issues noted in the 2003 Inspection report on file.

FUEL STORAGE:

Waste Oil Storage: Municipal dump **Owner/Operator:** Municipality of Rankin Inlet

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: NI	Water within Berms: NI	Evidence of Leaks: NI
Drainage Pipes: NI	Pump Station & Catchments Berm: Ni	
Pipeline Condition: NI	Condition of Tanks: Metal tanks: NI	

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator: No sampling results noted	
1		INAC: Municipal waste area, leachate outside of facility	
Signs Posted	SNP: none		Warning: U
Records & Reporting: Records were submitted for 2008.			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: The Hamlet of Rankin Inlet is currently unlicensed and has applied for a water license for the Waste Management area. The Municipality has hired a consulting firm to act on the Municipality’s behalf during this process. The Municipality of Rankin Inlet is required to have a Water License and currently is in non-Compliance as well has failed to adhere to a direction issued in 2008. Further enforcement actions are recommended.