



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Rankin Inlet	Tom Ng
Licence No. / Expiry	Representative's Title
3BM-RAN1214	Senior Administrative Officer
Land / Other Authorizations	Land / Other Authorizations
Date of Inspection	Inspector
June 18 th 2015	Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage
	<input checked="" type="checkbox"/> Other: Deposit of Waste

Conditions: **A - Acceptable** **C - Concern** **U - Unacceptable** **NA – Not Applicable** **NI – Not Inspected**

Water Use			Site Conditions			Haz/Mat Management		
Condition	Comment		Condition	Comment		Condition	Comment	
Intake/Screen	NA		Water Management Structures	A		Storage	A	1
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NI	
Source:	NA		Drainage	A		Spill Plan	NI	
Water Use:	NA		Erosion / Sediment	A				
Recirculation (y /n)	NA		Mitigation Measures	A	2	Administrative		
			Reclamation Activities	A		Records	NI	
			Materials Storage	A	3	Reports	NI	
Waste Disposal			Signage	A	4	Plans	NI	
Waste Water						Notifications	NI	
Solid Waste	C		Monitoring			Other		
Hazardous Waste	C		Sample Collection / Analysis					

**The number in the comments field will correspond with specific comments provided below.*

Samples taken by Inspector:	Location(s): Rankin Inlet Landfill
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

SECTION 1 ☐ Comments (s. __) ☐ Non-Compliance with Act or Licence (s. __) ☐ Action Required (s. __)

A compliance inspection was conducted on June 18th 2015 of Municipal water licence for the Hamlet of Rankin Inlet 3BM-RAN1214. Inspector was accompanied by Joe Kaludjak (Hamlet forman) and Megan Lusty (CGS).

SECTION 2 ☒ Comments (s. __) ☐ Non-Compliance with Act or Licence (s. __) ☒ Action Required (s. __)

Items noted during time of inspection.

1. Storage

Following a meeting where the Water Licence Compliance Working Group discussed its yearly goals, the Hamlet of Rankin Inlet committed to begin segregating hazardous material at the landfill. Discarded batteries have been collected and segregated from the landfill and stored in seacans (shipping container) until properly disposed of. AANDC encourages this practice.

2. Mitigation measures

During the time of the inspection the inspector noted that measures need to be taken to segregate waste oil drums and oil tanks, to prevent the spreading of waste oil by capping opened drums and stacking drums on pallets. **Hamlet foreman Joe Kaludjak informed the inspector that drums could be palletized and capped by July 14th 2015 to mitigate issue.**

3. Materials Storage

During the inspection, the hamlet foreman informed the inspector that measures were being taken to segregate material in the landfill. These measures will help prevent fires and the release of contaminants from the landfill.

4. Signage

Pervious inspections noted lack of signage at landfill, item required to help direct general public in segregation of material. Hamlet foreman informed and showed inspector that proper signage was on site and needed to be installed, lack of running equipment prevented from properly installing signs. **Foreman informed inspector that signage would be installed by August 31st 2015.**



SECTION 3


☐ Comments (s. __)

☐ Non-Compliance with Act or Licence, (s. __)

☐ Action Required (s. __)

During the writing of this inspection report all actions requested by inspector have all been addressed.

Yearly goals related to the deposit of waste in the Water licence compliance working group are being implemented.

Licensee or Representative	Inspector's Name
	Atuat Shouldice
Signature	Signature
	
Date	Date
	10/5/2015

Office Use Only:

Follow-up report to be issued by Inspector

☐ Yes ☒ No