

Licensee

WATER LICENCE INSPECTION FORM

Licensee Representative

| X | Original |
|---|------------------|
| | Follow-Up Report |

| Hamlet of Resolu | ite Bay | | Bhabesh Roy | | | |
|----------------------------------|----------------------|-------------------------|-------------------|------------------|-----------------|-------------------|
| Licence No. / Exp | oiry | | Representative | | | |
| 3BM-YRB1621 | | | Municipal Engi | | | |
| Land / Other Aut | thorizations | | Land / Other A | Authorizations | | |
| Data of Inspectio | | | Inchestor | | | |
| Date of Inspection July 19, 2021 | on | | Inspector | ith, and Jeremy | Fraser | |
| Activities Inspect | ted | | JOSEPH WIGHTEN | itii, and seremy | 114301 | |
| | | | | | | |
| Camp | Drilling | Mining | Construc | tion Rec | lamation [| Fuel Storage |
| Roads/Hauling | 🔀 Other: Sewag | ge Disposal Facility | Other: | | | |
| | | | | | | |
| Conditions: | A- Acceptable | U-Unacceptable | C-Concern | NI-Not Ins | pected | NA- Not applicabl |
| PART: | | | | Item No.* | Condition | Observation No.* |
| | A: SCOPE, DEFI | INITIONS AND ENFOR | CEMENT | | А | |
| B: GENERAL CON | IDITIONS | | | | С | |
| C: CONDITIONS A | APPLYING TO SECUI | RITY | | | NI | |
| D: CONDITIONS | APPLYING TO WAT | ER USE | | | Α | |
| E: CONDITIONS | APPLYING TO WAS | TE DISPOSAL AND MA | NAGEMENT | | С | 1-6 |
| F: CONDITIONS A | PPLYING TO MODI | FICATIONS | | | NI | |
| G: CONDITIONS | APPLYING TO CON | STRUCTION | | | С | |
| H: CONDITIONS | APPLYING TO EME | RGENCY RESPONSE A | ND | | С | |
| CONTINGENCY P | LANNING | | | | | |
| I: CONDITIONS A | APPLYING TO ABAN | DONMENT, RECLAMA | ATION AND | | NI | |
| CLOSURE PLANN | ING | | | | | |
| J: CONDITIONS A | PPLYING TO MONI | TORING | | | С | |
| SCHEDULES | | | | | NI | |
| *The item num | ber corresponds w | ith specific conditions | s within the lice | nce and the obs | ervation numbe | er corresponds |
| | | with specific com | ments provided | l below. | | |
| Samples taken by | y Inspector: | Location(s): | | | | |
| ☐ Yes ⊠ No | | Latitude: 74° 42' | 00" N Longitude | e: 94° 50′ 00″ W | 1 | |
| | | · | | | | |
| SECTION 1 | Comments (s. |) Non-Com | npliance with Act | or Licence (s) | Action I | Required (s) |
| BACKGROUND A renewa | al Application for 3 | MB-YRB1621 was ack | knowledged by | the Nunavut Wa | ater Board on N | 1arch 30, 2021. |
| The licen | nce under which the | e facility operated, w | as issued on No | vember 30th, 2 | 003 and expired | d on November |

The licence under which the facility operated, was issued on November 30th, 2003 and expired on November 30th, 2021. The expired licence allowed for the use of water and the deposit of waste in support of a municipal undertaking that included the operation of a potable water treatment facility, solid waste disposal facility, and sewage treatment facility. The scope of the Renewal-Amendment Application, however, excluded the portable water supply facility and several other facilities and/or activities either discontinued or currently covered under distinct licences issued to the hamlet of Resolute Bay, Nunavut.

Inspector Statement

On July 19th, 2021 a water licence inspection was conducted by Water Resource Officer(WRO) Joseph Monteith, Crown Indigenous Relations and Northern Affairs Canada(CIRNAC) and hereafter referred as an Inspector, of the Resolute Bay ATCO Sewage Disposal Facility at the Resolute Bay Airport, Resolute, Nunavut.

It is noted that complete sets of photographs related to this inspection will accompany this report as a supplement at



a later date once the photographs do become available.

General Condition

On January 27th, 2021 Robin Ikkutislu of the Nunavut Water Board emailed the Inspector Monteith a copy of Resolute Bay Airport's 2020 Annual Report satisfying part B - item 1 of the Water Licence.

Sewage Disposal Facility

- 1. The Sewage Disposal Facility is a non-engineered 3 cell lagoon(photo 1).
- 2. Two yellow triangle signs were observed contrary to Part B: Item 5(photo 3).
- 3. The sewage lagoon was partially empty at the time of the inspection. (See Photo #3).
- 4. Signs of historical over flow were observed, and observable from satellite photo (photo 1).
- 5. Signs of Slumping and Erosion were observed. The state of the walls appears to have gone into further decline.
- 6. No Flow metre on water intake or waste discharge. On November, 2020 Bhabesh Roy, Community Government and Services(CGS) with the Government of Nunavut emailed the Inspector Monteith an excel spreadsheet copy of the Water Consumption Report for the months of January 2020 to September 2020 listing Resolute truck consumption numbers total of 3013509 litres consumed. This figure should be articulated as the amount discharged into the Sewage Disposal Facility(photo 4).

| Comments | |
|----------|--|
|----------|--|

Non-Compliance with Act or Licence

Non-Compliance with Act or Licence

Action Required

Action Required

- -Label the two monitoring posts as listed in the water licence
- -Maintain the 1 metre free board at the Sewage Disposal Facility
- -Repair the walls of the Sewage Disposal Facility

Comments

- -Notify WRO Monteith at Joseph.Monteith@rcaanc-cirnac.gc.ca when decanting the Sewage Disposal Facility.
- -Report to the Spill Line when overflow is observed at the Sewage Disposal Facility
- -The licensee is reminded to remain diligent to prevent waste from entering water, the environment and to adhere to the discharge criteria listed in the licence.

| SECTION 3 | |
|--------------|---|
| Part B: Item | 5 |

The licensee shall, within ninety (90) days after the first visit by an Inspector and following issuance of the licence, post the necessary signs to identify the stations of the "Monitoring Program". All erected signage postings shall be in the official languages of Nunavut.

Part D: Item 5

The licensee shall advise an Inspector at least ten (IO) days prior to initiating any decant of the Sewage Disposal Facility.

Part D: Item 6

The Sewage Disposal Facilities shall be maintained to the satisfaction of an Inspector, and operated in such a manner as to prevent erosion and structural failure.

| Licensee or Representative | Inspector's Name |
|----------------------------|-------------------|
| Bhabesh Roy, Todd MacKay | Joseph Monteith |
| Signature | Signature |
| | food Auto L. |
| Date | Date |
| | November 25, 2021 |

CC: Licensing Department, NWB

Justin Hack, Manager of Field Operations, CIRNAC



Photo Log









| | oto Log # oto 4 | | | | | | | | Location ATCO Se | wage Lag | goon. Re | solute B | av. NU | | | |
|----|--------------------|------------|------------|--------------|------------------|----------------|----------------|--------------|---------------------|--------------|------------|----------|----------|-------------|-------------|----------|
| 1 | А | В | С | D | E | F | G | Н | |] | K | L | M | N | 0 | Р |
| 1 | | | | Resolute Bay | Truck and Utilio | dor water cons | umtion for 202 | 1 | | | | | | | | |
| 2 | | | | | months | | | | | | | | | | | |
| 3 | Community | January | February | March | April | May | June | July | August | September | October | November | December | Total | Av. Monthly | Av.daily |
| 4 | RB - Truck | 327,774 | 395,465 | 697,372 | 504,617 | 566,899 | 458 247 | plant bypass | nlant hynass | nlant hynass | 63,136 | | | 3,013,509 | 430,501 | 10,045 |
| | RB - Utilidor | 25,867,018 | | | | | | | | | | | | 165,812,847 | | |
| 7 | ND - Utiliaui | 23,007,010 | 19,227,012 | 13,042,433 | 13,303,231 | 21,000,400 | 20,301,303 | 3,333,414 | 23,230,202 | 32,140,577 | 40,014,700 |) | | 103,012,047 | 23,034,333 | 332,703 |
| 8 | | | | | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | | | | | |
| 18 | | | | | | | | | | | | | | | | |
| 19 | | | | | | | | | | | | | | | | |
| 20 | | | | | | | | | | | | | | | | |

