

**Folders**

Last Refresh:  
Mon, 1:02 pm  
(Check mail)

- **INBOX** (10)  
[Drafts](#)  
[Sent](#)  
[Trash](#) (Purge)

[Sign Out](#)

[Compose](#) [Addresses](#) [Folders](#) [Options](#) [Search](#) [Help](#) [SquirrelMail](#)

**Viewing a text attachment - [View message](#)**

[View Unsafe Images](#) | [Download this as a file](#)

Hello Joe,

The following is the account of the fuel leak at the Resolute Bay Airport. You may contact the mechanic (Sylvain Grimard) at (450) 479- 6510. If you have any other questions, do not hesitate to contact me.

Take Care,

Pat

To whom it may concern,

The fuel leak at Resolute Bay Airport was discovered on or about November 28, 2008. Terry (?), the plane re-fueller who works for Aziz Kheraj, reported the problem when there was not enough fuel pressure in the hose to put fuel in the planes.

The mechanic, Sylvain Grimard, was sent to find the problem. The following is from a signed statement given to me by Mr. Grimard on December 13, 2008.

***“Morgan (another of Aziz Kheraj’s employees) and I were sent out to the airport to find the leak at the pumping station. When we got there, oil was on the ground around the buildings. The oil covered an area 60 feet by 30 feet and was about four inches deep. We fixed a small leak in the hose reel. I went to the pump-house to close the valve and found a stream of oil about 1.5 to 2 inches in diameter leaking from near the pump. The leak was hitting the ceiling in the pump-house. I shut off the valve and fixed the leak the next morning”.***

***“While I was fixing the main leak the next morning, Morgan stepped on the drain pipe from the filter and broke it. This leaked about 45 gallons (200 litres) more oil on the floor. I had to install a cork gasket***