



BATHURST

INLET LODGE • DEVELOPMENTS • ARCTIC SERVICES

Contingency Planning and Spill Reporting in Nunavut for Bathurst Inlet Lodge / Bathurst Inlet Developments (1984) Ltd

Person in Charge:

Boyd Warner
President/ Partial Owner
Bathurst Inlet Lodge
Box 820 Yellowknife, NT X1A 2N6
Ph 867 873 2595
Fx 867 920 4263
Email info@bathurstinlet.com

Nunavut Water
Board

MAR 23 2009

Public Registry

In the absence of Boyd Warner being on site the camp manager will be the first contact and they will have instructions on this plan and how to contact Mr. Warner.

Bathurst Inlet Lodge is located in the community of Bathurst Inlet; we purchase fuel from the Nunavut Government as needed. Therefore we do not have a large need for capacity. Sometimes however we do have clients staying at the lodge and we they bring in Jet fuel, diesel and propane. This fuel is then stored in natural depressions by the Government fuel tanks. Number of drums can vary from 1 – 150. Clients are responsible for the removal of all drums and required to sign an environmental waiver assuming all responsibility for any spills or damage of any kind.

We have spill kits located beside our fuel storage areas.

Typically the Lodge does not have any more then 20 205 litre drums stored at any one time, unless as per above a client comes in.

The type of chemicals are: P-50 and or P-40 (arctic diesel), regular gasoline, Jet A or B, Avgas (100LL) and propane. All are in 205 l drums except the propane which is in 100Lb bottles. Thus typically the Max volume for the lodge at any one time is 8200 litres (40 205 litre drums) of petroleum products and 2000 lbs of propane (20 100lb bottles).

Steps in case of spill:

If an individual or employee notices or causes a spill they (if properly trained) will take immediate steps to

Page 1

P.O. Box 820, Yellowknife, NT X1A 2N6
Tel.: (867) 920-4330 or (867) 873-2595 Fax: (867) 920-4263 e-mail: info@bathurstinlet.com



BATHURST

INLET LODGE • DEVELOPMENTS • ARCTIC SERVICES

stop the flow (if safe) and contain the spill. Boyd Warner (or designated person) will be notified as soon as possible and then the following steps will happen:

- 1) Site inspection / assessment
- 2) Remedial action will then start and will include use of spill kit.
- 3) All contaminated soil will be gathered and collected in a leak proof container
- 4) Spill report will be filled out and proper authorities notified.
- 5) Contaminated soil will then be set out for treatment or to Yellowknife for disposal.

It should be noted here that as we are dealing in a max size of 205 litres for any one container that any spills will not be of a "major" size.

For a camp site plan please see attached.

Boyd Warner, President, ph 867 873 2595 (or in his absence designated manager) is responsible for activating the contingency plan.

All senior staff that work at the lodge are familiar with dealing with minor spills.

Bathurst Inlet Lodge is a small organization. It is co-owned by an Inuit company called Kingaunmiut Ltd. At any one time several owners are on site that may include Allen Kapolak, Sam Kapolak, Robert Akolak. Robert and Allen are both trained fuel handlers for POL. All three as well as Boyd Warner have been at the lodge for 40 years and are extremely familiar with operations and have all received on the job training.

The lodge is equipped with a satellite phone (number varies from year to year) and we will report any spill immediately to the proper authorities.