



NWB Tools

Ida Porter &lt;ida.porter@nwb-oen.ca&gt;

---

## 7BL-BIL1215 Renewal Application

---

**Sonia Aredes** <sonia.aredes@nwb-oen.ca>

Tue, Dec 22, 2015 at 4:45 PM

To: Robin Ikkutisluk &lt;robin.ikkutisluk@nwb-oen.ca&gt;, Ida Porter &lt;ida.porter@nwb-oen.ca&gt;, Karén Kharatyan &lt;karen.kharatyan@nwb-oen.ca&gt;

Hi , please save this information to the PRMain in the Application folder

Thanks  
Sonia

----- Forwarded message -----

From: **Boyd Warner** <boydw@bathurstinlet.com>

Date: Wed, Dec 9, 2015 at 10:05 AM

Subject: RE: 7BL-BIL1215 Renewal Application

To: Sonia Aredes <sonia.aredes@nwb-oen.ca>

Dear Ms Aredes;

Attached please find a completed application for a water license as well as some other attachments.

I have noted that;

*"1. The Licensee shall submit for Board approval within sixty (60) days following issuance of the Licence, a revised Spill Contingency Plan, prepared in the format set out by the Consolidation of Spill Contingency Planning and Reporting Regulations R-068-93, addresses comments received by the parties and addresses or includes the following:"*

Can you please tell me if I need to submit this Spill Contingency Plan now or as per the above within 60 days of being issued a license?

I have included a aerial picture of the lodge for the boards information. It is VERY important to recognize that the lodge operates with the small community of Bathurst Inlet and not ALL the buildings in the attached photograph are owned by the lodge. All the buildings that are along the water front are owned by Inuit persons.

Thank you and I await your comments on this.

Sincerely,

---

**From:** Sonia Aredes [mailto:[sonia.aredes@nwb-oen.ca](mailto:sonia.aredes@nwb-oen.ca)]  
**Sent:** Thursday, December 3, 2015 3:08 PM  
**To:** Boyd Warner  
**Cc:** Licensing Department  
**Subject:** Re: 7BL-BIL1215 Renewal Application

Hello Boyd

I am writing you regarding the submission of a licence renewal application (the Application) for the Bathurst Inlet Lodge Project, Water Licence 7BL-BIL1215.

The following issues should be addressed in order to proceed further with the Application processing:

Renewal Application:

Please, submit a complete application form, the following should be addressed:

1. Block 9 of the Application (description of the Undertaking), please expand upon the description of the undertaking and list of planned activities.
2. Blocks 14 and 15 of the Application: These sections should clearly identify the types, characteristics, volumes and planned disposal method for the waste types generated by the undertaking.

Spill Contingency Plan:

Submit a revised Spill Contingency Plan, in the revised Plan the following should be addressed:

1. Title Page: include a title page, introduction, table of contents, page numbers, date of latest revision and effective date of the plan;
2. An Emergency Contact list for assistance, including AANDC, EC, DFO, GNDoe, KIA's and Nunavut 24 hour Spill Report Line;
3. Re-fuelling Operations: include re-fuelling operations, including preventative measures (i.e secondary containment such as drip trays, etc.);
4. Dates of Operation: the Licensee should notify the NWB as far in advance as possible as to when the lodge will be in operation.
5. Spills on Snow and Ice: the Spill Contingency Plan should contain a section on how the Licensee plans to deal with spills on snow and/or ice.
6. A list of all spill response equipment and supplies as well as spill kit contents;
7. A copy of the NTNU Spill Report Form and the Instructions for Completing the NTNU Spill Report Form

Once you have submitted the required information, I will contact NPC in order to ensure the Application does not need to be further assessed by NPC and the Application can proceed to the next stage of Application processing.

Regards

Sonia Aredes

Technical Advisor

On Mon, Nov 30, 2015 at 11:44 AM, Boyd Warner <[boydw@bathurstinlet.com](mailto:boydw@bathurstinlet.com)> wrote:

Hello Sonia;

Please let me know you got this message.

I would like to start the process to get Bathurst Inlet Lodge a new water license.

After you review the file please get back to me and let me know what is needed to proceed.

Thank you.

Boyd Warner

President

Bathurst Inlet Lodge

Bathurst Inlet, Nunavut

Mailing address C/O

Box 820

Yellowknife, NT

X1A 2N6

867 873 2595

[boydw@bathurstinlet.com](mailto:boydw@bathurstinlet.com)

---

**From:** Phyllis Beaulieu [mailto:[phyllis.beaulieu@nwb-oen.ca](mailto:phyllis.beaulieu@nwb-oen.ca)]

**Sent:** Friday, November 27, 2015 1:40 PM

**To:** Boyd Warner

**Cc:** Licensing Department; Sonia Aredes

**Subject:** Re: 7BL-BIL1215 Renewal Application

Good afternoon Boyd, please be advised that Brady is no longer employed with the NWB and this file has been transferred over to Sonia Aredes as the technical Advisor. The last correspondence that was sent to you by Brady is attached for your reference. Perhaps you tried sending documents in but they should have bounced back to you as Brady is no longer here.

If you did try to send information in please redirect to [licensing@nwb-oen.ca](mailto:licensing@nwb-oen.ca)

Sonia may have additional requests for info after she's had a chance to review the file to date.

Regards,



On Fri, Nov 27, 2015 at 11:43 AM, Boyd Warner <[boydw@bathurstinlet.com](mailto:boydw@bathurstinlet.com)> wrote:

To Whom it May Concern

I wrote a email to Brady MacCarl on Nov 16 and 18<sup>th</sup> regarding a new license for Bathurst Inlet Lodge.

I have not heard back from here yet and was wondering if she is away or ?

We would like to start our application for a water license so if you can kindly advise who I should be contacting that would be appreciated.

Sincerely,

Boyd Warner

President

Bathurst Inlet Lodge

Bathurst Inlet, Nunavut

Mailing address C/O

Box 820

Yellowknife, NT

X1A 2N6

867 873 2595

[boydw@bathurstinlet.com](mailto:boydw@bathurstinlet.com)

---

**3 attachments**



**lodge areal 2005.jpg**  
322K



**100401-Application\_for\_Water\_Licence\_Renewal-OEDE-edited130401.doc**  
289K



**Other supplementary information.docx**  
12K