



7BL-BIL1215 Compliance Status

Sonia Aredes <sonia.aredes@nwb-oen.ca>
 To: Ida Porter <ida.porter@nwb-oen.ca>

Wed, May 25, 2016 at 2:32 PM

Hi Ida

Please, could you upload this email under the Compliance folder. It also has a document attached: Revision of Inspection Direction by INAC's inspector, this document should also be uploaded

Thanks
 Sonia

----- Forwarded message -----

From: **Andrew Keim** <Andrew.Keim@aandc-aadnc.gc.ca>
 Date: Thu, Feb 18, 2016 at 9:42 AM
 Subject: Re: FW: 7BL-BIL1215 Compliance Status
 To: Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>, Boyd Warner <boydw@bathurstinlet.com>
 Cc: Erik Allain <Erik.Allain@aandc-aadnc.gc.ca>, sonia.aredes@nwb-oen.ca

Good morning all,

Eva , thank you for the opportunity to speak to this issue directly with all parties.

Attached please find a copy of the Revised Direction issued to Bathurst Inlet lodge on October 27th, 2014.

This revision was issued subsequent to a telephone conversation between Mr. Warner, Mr. Erik Allain and myself where the Licensee, Mr. Warner had requested an extension to the original Direction.

Mr. Warner indicated in that conversation that he was in the process of working with the Government of Nunavut to address the issue of the Barrels and the Contaminated soils.

It was felt at the time that an extension to the date for compliance would facilitate the clean up.

The Revised Direction remains in effect and has not been rescinded as neither the Licensee nor the Government of Nunavut yet provided evidence of compliance as required by the Direction.

An Inspection was conducted this past summer and it confirmed that work had been undertaken by Government of Nunavut contractors and the Licensee to crush and consolidate the drums on site. However, this office has not yet been provided proof the Drums have been removed from site as required. It was felt that because some work to achieve compliance with the Direction had been undertaken that further actions may not be required at this point, however the file remains open.

This information was communicated to the Nunavut Water Board (Sonia Aredes) earlier this month and as we have seen in the past, the Board may chose not to renew the Water Licence based on the Compliance record of the Licensee.

That decision will be up to the Board.

I would be happy to discuss this or any other issues of compliance at any time.

Respectfully,

Andrew Keim

Field Operations Unit

Indigenous & Northern Affairs Canada
Affaires Autochtones et du Nord Canada
Nunavut Regional Office

P.O. Box 100

Iqaluit, Nunavut X0A 0H0

Andrew.Keim@aandc-aadnc.gc.ca

Phone: (867) 975-4289

Fax: (867) 979-6445

B.B (867) 222- 6488

>>> Eva Paul 2/17/2016 6:28 PM >>>

Hi Boyd,

Andrew (copied above) is the last inspector on record on this file. I'm hoping he can speak to the issue.

Andrew, please copy me on your response, thanks.

Eva

Eva Paul

Water Resources Officer | Agent des ressources en eau

Indigenous and Northern Affairs Canada | Affaires autochtones et du Nord Canada

PO Box 1500 | CP 1500

4923-52 St | 4923-52e Rue

Yellowknife, NWT | Yellowknife, TNO

X1A 2R3

Phone | Tél.: 867-669-2438

Cell | Mobile: 867-222-6490

Fax | Télec: 867-669-2702

Eva.Paul@aandc-aadnc.gc.ca

>>> "Boyd Warner" <boydw@bathurstinlet.com> 2/15/2016 11:06 AM >>>

Hello Eva;

Are you still the inspector for Bathurst Lodge?

Please see below as we need this corrected as soon as possible as it is holding up our license renewal.

Thank you.

Boyd Warner

President

Bathurst Inlet Developments (1984) Ltd

P.O Box 820

Yellowknife, NT

XOE 2N6

867 873 2595

boydw@bathurstinlet.com

From: Boyd Warner [mailto:boydw@bathurstinlet.com]

Sent: Friday, February 12, 2016 4:11 PM

To: 'Sonia Aredes'

Cc: 'Robin Ikkutisluuk'

Subject: RE: 7BL-BIL1215 Compliance Status

Importance: High

Thank you Sonia and if you will read all the emails in the file regarding this you will see clearly that while the lodge was accused of this issue of old drums and the removal we always have and still claim it was false and based on incorrect information.

The drums in question are the responsibility of the GN department of POL. Not the lodge.

This last summer the GN had all the drums crushed, palletized and they are waiting for removal but our still on site (but not on the lodges land).

Again I must say that this in no way should affect the lodges application for a water license and they are not the lodges nor ever have been our responsibility.

Sincerely,

Boyd Warner

President

Bathurst Inlet Lodge

Bathurst Inlet, Nunavut

Mailing address C/0

Box 820

Yellowknife, NT

X1A 2N6

867 873 2595

boydw@bathurstinlet.com

From: Sonia Aredes [mailto:sonia.aredes@nwb-oen.ca]

Sent: Friday, February 12, 2016 3:50 PM

To: Boyd Warner

Cc: Robin Ikkutisluq

Subject: 7BL-BIL1215 Compliance Status

Hi Boyd

Thanks for your submission. Your Application Submission is ready to go out for reviewer's comments and start the licensing process.

There is still an issue to be clarified with respect to this file. Associated to this file there is an Inspector Directions Report filed by INAC dated August 26, 2013 and reissued on October 28, 2014. The Directions are regarding the site cleanup and removal of old fuel barrels to be sent off -site.

I have contacted and asked INAC's Inspector with regard to this issue. INAC's Inspector has confirmed that the old barrels of fuel have been crushed and moved to a location for transport to the barge. There is not confirmation whether the barrels have been shipped off site. Please, could you provide an update regarding this matter.

Regards

Sonia Aredes

 **IQALUIT-#867605-v1-IQALUIT-#705893-V2-REVISED-_DIRECTION_
BATHURST_INLET_LODGE_AUGUST_2013__PDF.PDF**
480K