



Field Operations
Nunavut Regional Office
PO Box 100
Iqaluit, NU X0A 0H0

August 20, 2012

Mr William L. Lyall
B&J Fly-Fishing Adventures
PO Box 1329
Cambridge Bay, NU X0B 0C0
By Fax: 867-983-2203

RE: NWB Licence No. 7BL-EKK1015

Dear Mr. Lyall,

I recently was present at your site on July 13, 2012. Please find attached the report of my inspection. There is one matter that needs attention: the fuel barrel on-site should be placed in a berm in case it leaks, and covered over to keep the berm free of water/snow. I would like this done before next spring. Also, Annual Reports must be submitted every year whether or not the site is used. Please submit photos of the fuel placed in a covered berm with your annual report.

Please feel free to contact me to discuss this if you have any questions. I will include photos of the inspection when I send the hard copy of this report by mail.

Thank you,

Eva Paul
Water Resources Officer

Phone: 867-975-4548
Fax: 867-979-6445
Mobile: 867-222-6490
E-mail: Eva.Paul@aadnc-aadnc.gc.ca

Cc: Andrew Keim, A/Manager, Field Operations, Nunavut Regional Office
Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board



WATER USE INSPECTION REPORT

Date: July 13 2012	Licensee Rep. (Name/Title): N/A
Licensee: B&J Flyfishing Adventures	Licence No.: 7BL-EKK1015

Corrected coordinates: N69 24 04.5 W106 17 25.4

WATER SUPPLY

Source(s): Ekaluk River	Quantity used: unknown
Owner:/Operator: William Lyall	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NI	Storage Structure: NI	Treatment Systems: NI	Chemical Storage: NA
Flow Meas. Device: NI	Conveyance Lines: NA	Pumping Stations: NA	Screen : NI

Comments: Camp is currently shut down. Water intake and storage tanks are not evident. Camp looks very clean.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Outhouse

Natural Water Body: -	Continuous Discharge (land or water): -
Seasonal Discharge: -	Wetlands Treatment: - Trench: -

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: A
Discharge Meas. Device: NI	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NI
Discharge: NA	Effluent Discharge Rate: NA	

Comments: Outhouse is in good shape despite the door being open. I left it closed. No evidence of the sump for grey water.

Solid Waste:

Owner/Operator:

Landfill: NA	Burn & Landfill: NA	Other: Backhaul
---------------------	--------------------------------	------------------------

Comments: No garbage lying around, only at nearby sites. Empty propane tanks and fuel barrels should be hauled out.

FUEL STORAGE:

Waste Oil Storage:

None

Owner/Operator: Licensee

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: U	Water within Berms: NA	Evidence of Leaks:
Drainage Pipes: NA	Pump Station & Catchments Berm: NA	



Berms & Liners: U	Water within Berms: NA	Evidence of Leaks:
Pipeline Condition: A	Condition of Tanks: A	

Comments: Propane tanks should be fixed in place against buildings so they cannot fall over. The one fuel barrel I found on site is not in a secondary containment. A small berm should be placed under the fuel barrel to avoid any potential for spills as the site is unattended for most of the year.

Non-Compliance of Act or Licence:

Annual report for 2011 should be filed with the NWB as per the licence conditions, even if no activity occurred on site. Backhaul of empty tanks is recommended. Fuel on site is to be placed in secondary containment in case of leaks. As there is only one barrel on-site and there is currently no evidence of leaking, this work can be delayed until it is practical, preferably before winter. Please photograph the improvement and submit with Annual Report.

Eva Paul

Inspector's Name



Inspector's Signature